

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : THIF	RD PARTY	Vehicle No.	: FBK5629Y
		Make & Model	: HONDA CB400X
		Year of Manufacture	:
		Chassis No.	:
Ins Company : FIRST CAPITAL		Engine No.	:
Excess :		Policy No.	: D-21097290MFCE/103
Date of Accident : 20	/06/2021	Time of Accident	: <u>'06:45 HRS</u>
Suggested Days of Repair :		In-house Vehicle Assessor	
Repair Estimates		Case Owner	:
Parts (a) Cost / List Price Items	\$ 34,640.00	Signature	:
Plus/Less	\$ -	Contact No	
	· · · · · · · · · · · · · · · · · · ·		
Total of Cost / List	\$ 34,640.00		
(b) Nett Price Items	\$ 938.00		
Less			
Total of Nett Item			
(c) Special Nett Items	<u> </u>		
Total Parts Cost (Appendix A)	\$ 34,640.00		
Labour (Appendix B)	\$ 1,400.00		
Total Repair Cost	\$ 36,040.00		
The above total will be subjected to 7% G.S.T.			
Name of Surveyor			
Company	:		
Survey conducted on	:	at	
Remarks By Surveyor			
(a) The repair of this vehicle is authorized / is not authorized until further notice.			
(b) Recommended Days of Repair: day(s)			
(c) Resurvey	: Required / Not Required		
(d) Excess	:\$		
	-+		
(e) Signature of surveyor	:	Date:	