



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : THIRD PARTY

Vehicle No. : FBK6029Y

Make & Model : HONDA CB400X

Year of Manufacture : _____

Chassis No. : _____

Engine No. : _____

Policy No. : D-21097290MFCE/103

Time of Accident : '06:45 HRS

Ins Company : FIRST CAPITAL

Excess : _____

Date of Accident : 20/06/2021

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Contact No : _____

Parts (a) Cost / List Price Items \$ 43,140.00

Plus/Less _____ \$ -

Total of Cost / List \$ 43,140.00

(b) Nett Price Items \$ 938.00

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 43,140.00

Labour (Appendix B) \$ 1,800.00

Total Repair Cost \$ 44,940.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____
Company : _____
Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : FBK6029Y Case Owner : 0

Make & Model : HONDA CB400X Year Manufacture : 0

Chassis No : 0 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : THIRD PARTY

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	RIGHT HAND SWITCH	1		\$ 350.00	x nn		
2	LEFT HAND SWITCH	1		\$ 250.00	/ BR		
3	THROTTLE CABLE SET	1		\$ 120.00	x nn		
4	CLUTCH LEVER	1		\$ 60.00	/ BT		
5	HEADLIGHT ASSY	1		\$ 850.00	x nn		
6	RECEIVER UNIT	1		\$ 280.00	x nn		
7	HANDLE BAR	1		\$ 180.00	/ BT		
8	STEERING CONE SET	1		\$ 220.00	/ nec		
9	FRONT FENDER W BRACKET	1		\$ 330.00	x nn		
10	FRONT TYRE	1		\$ 180.00	x nn		
11	FRONT FORK ASSY	1		\$ 1,800.00	/ BT		
12	FRONT BRAKEPAD	1		\$ 65.00	x nn		
13	FRONT CALIPER ASSY	1		\$ 600.00	x nn		
14	FRONT WHEEL ASSY (W SHAFT & DISC)	1		\$ 1,105.00	/ cut		
15	REAR WHEEL SHAFT	1		\$ 75.00	/ BT		
16	REAR WHEEL SPROCKET & HUB SET	1		\$ 550.00	/ nec		
17	REAR DRIVE CHAIN	1		\$ 180.00	x nn		
18	REAR TYRE	1		\$ 210.00	/ Tn		
19	REAR WHEEL ASSY	1		\$ 680.00	/ BR		
20	REAR WHEEL DISC	1		\$ 250.00	/ BT		
21	REAR CALIPER ASSY	1		\$ 750.00	/ BR		
22	REAR BRAKE PAD	1		\$ 65.00	/ MIS		
23	REAR WHEEL SPEED SENSOR	1		\$ 450.00	/ MIS		
24	FUEL PUMP UNIT	0		\$ 680.00	x nn		
25	FUEL TANK ASSY W BRACKET	1		\$ 1,660.00	/ DD		
26	SEAT ASSY WITH LOCK SET	1		\$ 710.00	/ BR		
27	REAR COWLING SET	1		\$ 290.00	/ BR		
28	SIDE COVER SET (LEFT & RIGHT)	1		\$ 240.00	/ BR		
29	EXHAUST ASSY SET W HEADER	1		\$ 2,530.00	/ DD		
30	GEAR PEDAL ASSY SET	1		\$ 450.00	x nn		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : FBK6029Y Case Owner : 0

Make & Model : HONDA CB400X Year Manufacture : 0

Chassis No : 0 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : THIRD PARTY

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	BRAKE PEDAL COMP	1		\$ 180.00	/ BT		
32	SIDE STAND ASSY SET	1		\$ 310.00	X nn		
33	REAR TAILLIGHT ASSY W BRACKET	1		\$ 570.00	/ BR		
34	REAR NUMBER PLATE LIGHT ASSY	1		\$ 150.00	/ BR		
35	MAIN STEP HOLDER SET W BRACKET	1		\$ 1,700.00	/ BT		
36	PILLION STEP BAR SET	1		\$ 250.00	/ BR		
37	REAR SWING ARM ASSY W SHAFT	1		\$ 1,425.00	/ BT		
38	CHAIN GUARD	1		\$ 95.00	X nn		
39	CHAIN ADJUSTER COMP	1		\$ 45.00	X nn		
40	REAR SHOCK ASSY SET	1		\$ 1,980.00	/ BT		
41	REAR REFLECTOR	1		\$ 60.00	/ mis		
42	REAR FENDER COMP	1		\$ 550.00	/ BR		
43	REAR TAILBOARD	1		\$ 350.00	/ BR		
44	BODY FRAME COMPLETE (FRONT & REAR)	1		\$ 8,500.00	/ BT		
45	RADIATOR ASSY SET	1		\$ 1,495.00	X n		
46	FRONT WINDSCREEN ASSY SET	1		\$ 680.00	/ BR		
47	FRONT HEADLIGHT COVER	1		\$ 150.00	X nn		
48	FRONT UNDERCOVER & COWLING	1		\$ 600.00	X nn		
49	FRONT METER PANEL ASSY	1		\$ 300.00	/ BR		
50	FRONT POSITION BULB LID	1		\$ 55.00	/ BR		
51	PUSH RIVET	1		\$ 15.00	/ nec		
52	INNER SHROUD COVER SET (LH & RH)	1		\$ 240.00	/ BR		
53	MIDDLE COWLING (LH & RH)	1		\$ 960.00	/ BR		
54	RADIATOR SHROUD COVER (LH & RH)	1		\$ 360.00	X nn		
55	UNDER COVER ASSY SET (LH & RH)	1		\$ 450.00	X nn		
56	BLINKER LIGHT & POLE	1		\$ 840.00	/ mis		
57	CRASHBAR (FRONT & REAR)	1		\$ 1,060.00	/ BT		
58	ENGINE GUARD	1		\$ 480.00	/ BT		
59	SIDE BOX W RACK	1		\$ 660.00	/ BR		
60	REAR DOCUMENT BOX W RACK	1		\$ 630.00	/ BR		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : <u>FBK6029Y</u>	Case Owner : <u>0</u>
Make & Model : <u>HONDA CB400X</u>	Year Manufacture : <u>0</u>
Chassis No : <u>0</u>	Engine No : <u>0</u>
Sales Order : <u>0</u>	Supplier : <u>0</u>
Order By : <u>0</u>	Type of Claim : <u>THIRD PARTY</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
61	FRONT SIGNAL LIGHT (LH & RH)	1		\$ 560.00	/ BR		
62	SIREN	1		\$ 950.00	/ BR		
63	FRONT & REAR WHEEL BEARING ASSY	1		\$ 330.00	/ nec		
64	DECAL	1			\$ 450.00	/ nec	
65	TOWING	1			\$ 50.00	/ nec	
66	CAMERA	1			\$ 438.00	/ MIS	
67	0	0					
68	0	0					
69	0	0					
70	0	0					
71	0	0					
72	0	0					
73	0	0					
74	0	0					
75	0	0					
76	0	0					
77	S	0					
78	0	0					
79	0	0					
80	0	0					
81	0	0					
82	0	0					
83	0	0					
84	0	0					
85	0	0					
86	0	0					
87	0	0					
88	0	0					
89	0	0					
90	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

6 days

Vehicle No.	: <u>FBK6029Y</u>	Case Owner	: <u>0</u>
Make & Model	: <u>HONDA CB400X</u>	Year of Manufacture	: <u>0</u>

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.