



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP11	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #07-03 Singapore 138498				
		Document Date 27/04/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	17/03/2017	SLL9863L	0	14799	75/DS/SLL9863L
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3X02007765		2NRX132282	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:XD4367K ACC DATE:27/04/22 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50	100.00
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAT TEST					180.00
3	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR					180.00
4	B	BP-LAB2 R/L REAR RIGHT DOOR MACH					720.00
5	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA					2880.00
6	B	BP-RES2 RESPRAY ACC AFF AREA					2950.00
7	1	K52159-0U908 COVER, RR BUMPER, L/	1.00	552.30			552.30
8	2	T67003-0D230 PANEL SUB-ASSY, RR	1.00	993.80			993.80
9	3	K67871-0D180 WEATHERSTRIP, RR DOO	1.00	191.00			191.00
10	4	K67841-0D350 COVER, RR DOOR SERVI	1.00	33.30			33.30
11	5	K75923-0D200 TAPE, BLACK OUT, NO.	1.00	50.90			50.90
12	6	K68142-0D200 RUN, RR DOOR GLASS,	1.00	106.70			106.70
13	7	K67407-0D160 BAR SUB-ASSY, RR DOO	1.00	130.50			130.50
14	8	K68180-0D240 WEATHERSTRIP ASSY, R	1.00	80.20			80.20
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd							
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others		Less		
					Amount Due		

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		M/S Grab Rentals Pte Ltd 3 Media Close #07-03 Singapore 138498 Work: 65703925			
			Document No.					
			0					
			Document Date					
			27/04/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	NSP151R	CEXRKT Q1	17/03/2017	SLL9863L	0	14799	75/DS/SLL9863L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFB29F3X02007765		2NRX132282	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	9	T61601-0D230 PANEL SUB-ASSY, <i>x R</i>			1.00	1082.90		1082.90
16	0	T21000-20 SIKA 182010 SIKATACK GO! (BLA <i>x nn</i>			1.00	108.00		108.00
17	1	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>x nn</i>			1.00	200.00		200.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____					<i>Steve (CLKK)</i> 28/4/22, 10.30am <i>W PL</i> <i>PIP</i> <i>My BCL sy</i> <i>5 days</i>			
For & on behalf of			Date:		Total		10,539.60	
Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary			
			Please acknowledge receipt of vehicle		Parts	3,529.60	GST 7.00%	737.77
					Labour	6,830.00		
					Sublet	180.00	Less	0.00
					Lubrication/Fluid	0.00		
					Others	0.00	Amount Due	11,277.37

Customer Copy