



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD C/O Crawford & Company 6 Shenton Way #19-10 OUE Downtown 2 SINGAPORE 068809			Ref: CS/CWF22003939/Kvy3e2 Date: 08/06/2022 Code: TMI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Bobcat Skid Loader	Veh. Inspected	SKW 320A
	Policy No.	1096294/G/TWC	Coverage (\$)	0.00
	Claim No.	G2201152	Excess (\$)	0.00
	Assign From	WEE CHIAU TAN	Assign Date	27/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA FIELDER (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	NRE1618000977	Colour	METALLIC SILVER
	Odometer	37110 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FALKEN	8 mm
	L/H Front Tyre	185/60 R15	FALKEN	8 mm
	R/H Rear Tyre	185/60 R15	FALKEN	8 mm
	L/H Rear Tyre	185/60 R15	FALKEN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/04/2022	Inspection Date	27/04/2022
	Survey held at	CHENG HOE MOTOR SERVICE 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	