



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03 SINGAPORE LAND
TOWER SINGAPORE 048623

Ref: CS/SMO22003941/Uvy3m4

Date: 03/06/2022

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBR 3907X	Veh. Inspected	SLF 7648L
Policy No.	D21MTMC01002648	Coverage (\$)	0.00
Claim No.	CMTD2201426/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/04/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11205077	Colour	RED
Odometer	124114 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55ZR17	HABILEAD	6 mm
L/H Front Tyre	215/55ZR17	HABILEAD	6 mm
R/H Rear Tyre	215/55ZR17	HABILEAD	6 mm
L/H Rear Tyre	215/55ZR17	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/04/2022	Inspection Date	27/04/2022
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**