



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|---|--|
| ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 | | | Ref: CS/AIS22003942/Any3m4 Date: 18/07/2022 Code: AIS | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLX 1702H | Veh. Inspected | SLW 3441C | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | 2022 22004651FR | Excess (\$) | 0.00 | |
| Assign From | SHANTI | Assign Date | 27/04/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI ELANTRA | c.c | 1591 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | KMHD841CMJU628366 | Colour | BLUE | |
| Odometer | 245335 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | ARIVO | 6 mm | |
| L/H Front Tyre | 195/65 R15 | ARIVO | 6 mm | |
| R/H Rear Tyre | 195/65 R15 | ARIVO | 6 mm | |
| L/H Rear Tyre | 195/65 R15 | ARIVO | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 23/04/2022 | Inspection Date | 26/04/2022 | |
| Survey held at | PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 11 Working Days | |