

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM22D202260/C01/TANKL Date: 31st May 2022

Our Ref : CS/CTI22003953/Evy3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMQ 2781Y ACCIDENT ON 31/03/2022

Instruction was received to inspect the vehicle Reg. No. SMQ 2781Y. The inspection was conducted on 28/04/2022 at the premises of M/s Wearnes Automotive Pte Ltd, 45 Leng Kee Road, Singapore 159103.

The following vehicle information was recorded:

Registration Number : SMQ 2781Y

Make/Model : Jaguar XJ 2.0 TSS SWB SR

Year of Registration : 2014 Body Colour : Black

Chassis Number : SAJAC12MXEPV74431

Engine Capacity : 1999 cc Speedometer Reading : 73097 km

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is \$\$35,720.50 (Sin Dollars: Thirty-Five Thousand Seven Hundred Twenty and Fifty cents only.) (Exclude check items \$\$1,252.50Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 100,000.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 76,308.00)

S\$ 23,692.00

Less: Excess (S\$ 1,250.00)

Nett Liability S\$ 22,442.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 35,720.50

(Exclude check items S\$1,252.50Nett)

Less: Excess (S\$ 1,250.00)

Nett Liability

S\$ 34,470.50

(a) - (b) = (S\$ 12,028.50)

The amount of estimated saving of S\$12,028.50 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

les.

CHEN TSUE YEE Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.