



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897		Ref: CS/AIS22003965/Uvy3n2 Date: 20/05/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKL 2520J	Veh. Inspected	SMY 3180H
Policy No.		Coverage (\$)	0.00
Claim No.	2022 22004626SL	Excess (\$)	0.00
Assign From	SHANTI	Assign Date	28/04/2022
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI OUTLANDER (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GF7W0701062	Colour	BLUE
Odometer	15882 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R18	TOYO	7 mm
L/H Front Tyre	225/55 R18	TOYO	7 mm
R/H Rear Tyre	225/55 R18	TOYO	7 mm
L/H Rear Tyre	225/55 R18	TOYO	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/04/2022	Inspection Date	04/05/2022
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	