



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22003993/Avy3n2	
			Date: 27/05/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBF 3237J	Veh. Inspected	SLV 1518J
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201398/SYH	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	28/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA C-HR HYBRID	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ZYX102065547	Colour	YELLOW
	Odometer	153850 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	WEST LAKE	6 mm
	L/H Front Tyre	225/50 R18	WEST LAKE	6 mm
	R/H Rear Tyre	225/50 R18	WEST LAKE	6 mm
	L/H Rear Tyre	225/50 R18	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	22/04/2022	Inspection Date	29/04/2022
	Survey held at	MTM PERFORMANCE AUTO PTE. LTD. 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB SINGAPORE 608586		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	