



A S AUTO SERVICE

No 1, Kaki Bukit Ave 6
#01-106/108 Autobay @ Kaki Bukit
Singapore 417800
Tel: 6744 8183
Co. Reg No: 53073291B

To Allianz Insurance Singapore Pte. Ltd.

Vehicle Number: SMW 5908Z
Date of Accident: 21/04/2022
Policy Number: SP2001284953

PARTS REPLACEMENT - SUPPLEMENTARY ITEMS	Qty	Unit Price	List Price \$	
Left Front Head Lamp Bracket <i>bt</i>	1	190.00	190.00	✓
Left Front Wheel Inner Fender (Cowling) <i>torn</i>	1	230.00	230.00	✓
Left Rear Shock Absorber <i>HH</i>	1	2100.00	2,100.00	X
Right Front Door Handle <i>broken</i>	1	595.00	595.00	✓
Right Front Door Trim <i>broken</i>	1	2350.00	2350.00	✓
Right Front Door Trim Upper Moulding <i>broken</i>	1	295.00	295.00	✓
Right Rear Wheel Inner Fender (Cowling) <i>torn</i>	1	430.00	430.00	✓
Rear Right Driveshaft <i>Done</i>	1	1800.00	1800.00	✓
Right Side Tyre <i>1 pc cut 1 pc HH</i>	2	580.00	1160.00 245.00	✓
Oxygen Sensor <i>Done</i>	1	483.00	483.00	✓
Vacuum Tank <i>minorly broken</i>	1	280.00	280.00	✓
Secondary Air Pump <i>broken</i>	1	1250.00	1,250.00	✓
Engine Lower Cover <i>damaged</i>	1	650.00	650.00	✓
Horn W/ Bracket <i>bt</i>	1	140.00	140.00	✓
Front Bumper Sponge <i>torn</i>	1	170.00	170.00	✓
Front Right Fog Lamp <i>damaged replaced</i>	1	180.00	180.00	✓
Front Sway Bar <i>bt</i>	1	650.00	650.00	✓
Grand Total			12,953.00	

Tgn

2kk Auto

9758.00

8