

Our Job Ref No : 305512813
Date : 26/04/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive, Singapore 608069
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Thevan
Vehicle Reg No. : SHC1133H

Fax :

14/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: ALLIANZ --- SMA9140K
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges \$0.00
 - Total for Part-By-Part Repair Cost
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$6,300.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : 28/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1133H

Make : Toyota

Model : Prius (G4A)

Date: 18/04/2022

Insurance: ALLIANZ

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER			\$ 503.04	Cut
10	REAR BUMPER CLIPS			\$ 22.00	pac
1	REAR BUMPER LOWER COVER			\$ 654.96	Cut
1	REAR BUMPER UNDER SIDE CENTRE COVER			\$ 654.96	X SUC
1	COVER FLOOR UNDER NO. 2			\$ 220.50	X SUC
1	REAR BUMPER UNDER SIDE COVER RH			\$ 232.00	X SUC
1	REAR BUMPER TOWING COVER			\$ 82.70	DRS
1	REAR BUMPER SIDE RETAINER LH			\$ 112.70	rec
1	REAR BUMPER REINFORCEMENT			\$ 378.32	X SUC
1	REAR BUMPER SIDE EXTENTION LH			\$ 148.40	X SUC
1	REAR END PANEL			\$ 738.96	X R
1	REAR END PANEL GARNISH			\$ 165.80	X SUC
1	BACK DOOR GARNISH SUB ASSY			\$ 1,054.71	CRA
1	REAR TRUNK LID LOGO (PRIUS)			\$ 62.14	rec
1	REAR TRUNK LID LOGO (HYBRID)			\$ 62.14	ne
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$ 81.43	rec
1	TAIL LAMP UPPER LH			\$ 557.90	CRA
1	TAIL LAMP LOWER LH			\$ 570.00	X SUC
1	REAR WINDSCREEN GLASS WITH MOULDING			\$ 1,884.32	rec
1	REAR TRUNK LID COVER			\$ 1,303.29	rec
1	REAR TRUNK LID GLASS			\$ 1,569.70	rec
2	REAR TRUNK LID HINGE LH RH		\$ 69.32	\$ 138.64	X SUC
1	REAR EXHAUST PIPE CENTRE INSULATOR			\$ 498.60	CR
1	REAR EXHAUST PIPE HANGER			\$ 40.70	X SUC
1	REAR EXHAUST PIPE			\$ 1,163.40	CR
	SUB TOTAL			\$ 12,901.31	
	LESS 30%			\$ 3,870.39	
	DISCOUNTED TOTAL			\$ 9,030.92	
1	PETROL ONLY STICKER			\$ 15.00	Nett / rec
1	REPLACE REAR BUMPER ADVERTISEMENT LOGO			\$ 50.00	Nett / rec
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$ 60.00	Nett / rec
1	REAR TRUNK LID APPS STICKER			\$ 40.00	Nett / rec
1	REAR BUMPER RUBBER MAT			\$ 50.00	Nett / rec
1	REAR REVERSE SENSOR			\$ 135.70	Nett / rec
				\$ 350.70	Nett / rec Cut
	Labour Charge				
	PANEL BEATING			\$ 1,400.00	700
	SPRAY PAINTING CHARGE			\$ 1,100.00	750
	TOWING FEE			\$ 60.00	
	CHECK ALL LIGHTING			\$ 60.00	30
	TUFF KOTE			\$ 80.00	30
	REMOVE/ REFIX EXHAUST PIPE			\$ 150.00	X R N
	REMOVE/ REFIX REAR WINDSCREEN GLASS			\$ 120.00	
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00	30

Qty	Parts Description / Labour	Type	Unit Price	Amount
	TOTAL LABOUR			\$ 3,030.00
	ESTIMATE TOTAL			\$ 12,411.62
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Thuan
 82235169
 19/4/22 1730
 L/S 3clays wp

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: