

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS3/CTI22004011/Rty3	
	3 ANSON ROAD # SPRINGLEAF TOV		Date:	28/04/2022		
				Code:	СТІ	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 1256L	Veh. Inspected	k	YQ 374K	
	Policy No.	DMCVSNA00147682100	Coverage (\$)		0.00	
	Claim No.	SNM22D202876/C02/XE1256L/ TANKW	Excess (\$)		0.00	
	Assign From	BILLY TAN	Assign Date		28/04/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description of Damages				
5.	General Information					
	Accident Date	27/04/2022	Inspection Dat	e	28/04/2022	
	Survey held at	GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					