



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22004040/Uty3m4 Date: 01/06/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SLK 3852M	
	Policy No. Z22VP05030635	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	4,000.00	
	Assign From GERALD POH	Assign Date	29/04/2022	
2. Vehicle Particulars & Condition				
	Make & Model MITSUBISHI LANCER EX	c.c	1590	
	Engine No. HIDDEN	Year of Reg.	2017	
	Chassis No. JMYSRCY1AGU006032	Colour	GREY	
	Odometer 93048 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	FALKEN	6 mm
	L/H Front Tyre	205/60 R16	FALKEN	6 mm
	R/H Rear Tyre	205/60 R16	FALKEN	6 mm
	L/H Rear Tyre	205/60 R16	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 28/04/2022	Inspection Date	29/04/2022	
	Survey held at SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
	A) THE MARKET VALUE IS S\$53,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	