

Certification for Bus Repairs



CBR REF NO. : HG20220214

Depot : HG **Report No.:** W53152021 **BUS VEHICLE NO. :** SG5515L
Driver's Co no. & Name : 79657 Chok Kian Hua
Accident Date : 06/12/2021

Date in : 06/12/2021

Date Out : 04/01/2022

Yr Of Reg	Make / Model	Chassis No.
2017	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P925HA183185

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30750014	PANEL.REAR BUMPER.O/S	1	\$160.00
30750006	DOOR RETAINER;EXTERIOR DOOR	1	\$35.00
30311711	NUMBER PLATE RECESS PAN;EXT.RR	1	\$168.00
30750012	EXTERIOR RR O/S CORNER;F/GLASS	1	\$817.00
30750041	SIDE SHEETMETAL PANEL	1	\$212.00
30750210	BOTTOM BOOT DOOR ASSY;RR ENG DR	1	\$1,274.00
30750435	O/S LOWER COOLER DOOR ASSY	1	\$1,470.00
30541765	LED LICENSE PLATE LAMP	2	\$42.00
30541726	LED INDICATOR LIGHT 24V;30541714 1 LED	1	\$67.00
30541727	LED STOP/TAIL LIGHT 24V;30541713 1 LED	1	\$69.00
30541715	REAR REVERSE LAMP;B9TL EU5	1	\$81.00
30750013	PANEL.REAR BUMPER.N/S	1	\$160.00
30750142	REAR ENGINE COMPARTMENT DOOR	1	\$3,104.00

TOTAL FOR PARTS		S\$	7659.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	184.00
2	Contractor's repair charges	S\$	2600.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$	2784.00
Repair cost of Advertisement / Livery		S\$	-
TOTAL DAMAGE		S\$	10443.00

Certification for Bus Repairs



CBR REF NO. : HG20220214

Depot : HG

Report No.: W53152021

BUS VEHICLE NO. : SG5515L

Driver's Co no. & Name : 79657 Chok Kian Hua

Accident Date : 06/12/2021

Date in : 06/12/2021

Date Out : 04/01/2022

Yr Of Reg	Make / Model	Chassis No.
2017	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P925HA183185
TOTAL DAMAGE		S\$ 10443.00
Overheads		S\$ 3132.90
Towing Charges		S\$ -
Repair Period : 6 day(s)	Loss of Use	S\$ 2500.80
TOTAL LOSS		S\$ 16076.70

Prepared By : Aw Boon Huan

Date : 21/02/2022

Approved By
Workshop Mgr : Aw Boon Huan

Date : 21/02/2022

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 16076.70

Acknowledged By
Depot Safety : Ang Kiat Siang

Date : 22/02/2022

* This is computer generated document and does not require signature