

⏪

⏩

1 of 2 ?

⏴

⏵

100%

⏴

⏵

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA21012941/T1qf3 Date: 21/12/2021 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 4085P	Veh. Inspected	SG 5515L
Policy No.		Coverage (\$)	0.00
Claim No.	NSV2100163/HLF	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	21/12/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/12/2021	Inspection Date	21/12/2021
Survey held at	SBS TRANSIT LTD (Branch) 4 DEFU LANE 1 SINGAPORE 539536		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			