

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 13 May 2022 11:59 AM
To: Hasrianah Binte Hassan
Cc: SUR; Catherine Chong Kai Ling
Subject: MSIG-OD YP 3896G DOA: 28/04/2022

Dear Hasrianah,

As instructed by our client, please proceed to repair the insured vehicle **YP 3896G at repair cost not more than \$42,000.00 on part by part (all in). (Excess \$700/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)