

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	Ref:	CS/AGI22004060/Kqy3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	Oate:	15/06/2022	
			C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLX 5374U	Veh. Inspected		SHF 597T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10014986/JM	Excess (\$)		0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date		29/04/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS (A)	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	JTDKB3FU103093835	Colour		M.P. WHITE / RED	
	Odometer	90915 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	FIRENZA		6 mm	
	L/H Front Tyre	195/65 R15	FIRENZA		6 mm	
	R/H Rear Tyre	195/65 R15	DUNLOP		3 mm	
	L/H Rear Tyre	195/65 R15	DUNLOP		3 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/04/2022	Inspection Date		29/04/2022	
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: