



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref	: WH1157
Vehicle No.	: SMN6024P
Make & Model	: TOYOTA PRIUS PLUS (AUTO)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Bonnet ✓ BUC		250.00	
1	Bonnet lock ?		70.00	
1	Front bumper logo badge ✓ NEC		50.00	
1	Front bumper top rubber seal ?		40.00	
2	Front bumper side retainer LH/RH @2*\$45 ?		90.00	
1	Front bumper sponge ?		70.00	
1	Front bumper reinforcement ?		180.00	
2	Headlamp LH/RH @2*\$800 ?		1600.00	
1	Radiator top garnish ?		120.00	
1	Wiper top side garnish RH ?		35.00	
1	Front bumper ✓ DE		240.00	
1	Center grille ✓ CRA		170.00	
1	Front bumper lower grille ?		190.00	
1	Bonnet hinge LH/RH @2*\$30 ?		60.00	
1	Front Fender LH (Repair refer to labor)		0.00	
1	Front door LH (Repair refer to labor)		0.00	
1	Towing cover (Repair refer to labor)		0.00	
1	Support Panel (Repair refer to labor)		0.00	
Part Items Total:			3165.00	
			10%	
			316.50	
			3481.50	
<u>SPECIAL NETT ITEMS</u>				
1	Front bumper clips ✓ NEC		35.00	
1	Bonnet Insulator clips ✓ NEC		35.00	
1	Center grille clips ✓ NEC		35.00	
1	Front car plate with Holder ✓ CUT		35.00	
SN Items Total:			140.00	
Total Parts:			3621.50	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1157
Vehicle No.	: SMN6024P
Make & Model	: TOYOTA PRIUS PLUS (AUTO)

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	600
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
Labour Total :		2060.00	
TOTAL (PARTS & LABOUR):		5681.50	



4 Days

Part by part

Before paint photos

Excess: TBA

Not Authorised

Guo Qiang - LKK

82880282

04/05/2022

GuoQiang@lkkauto.com