

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 06 Jul 2022

Preliminary Advice

Insured Vehicle No : YN7332B
TP Vehicle No : SNB184B
Make : TOYOTA PRIUS
Date of Inspection : 29/04/2022
Inspection At : MY CAR CONSULTANT PTE LTD (JALAN LAM HUAT) (HQ)
60 JALAN LAM HUAT, CARROS CENTRE #05-21
SINGAPORE 737869
Accident Date : 22/04/2022
Assignment Date : 29/04/2022
Est. Duration of Repair : 2

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,776.75
Revised Amount	:S\$	280.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	280.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.