



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH			Ref: CC4/ASM22004076/Apa3q2 Date: 01/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKP 4799M	Veh. Inspected	SCR 6886R
	Policy No.	GA549885	Coverage (\$)	0.00
	Claim No.	S2M03ZTJ	Excess (\$)	0.00
	Assign From		Assign Date	29/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA45	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WDD1173522N050400	Colour	BLUE
	Odometer	122170 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	265/35 R19	GOODYEAR	6 mm
	L/H Front Tyre	265/35 R19	GOODYEAR	6 mm
	R/H Rear Tyre	265/35 R19	GOODYEAR	6 mm
	L/H Rear Tyre	265/35 R19	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/04/2022	Inspection Date	13/06/2022
	Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	