

Claim Audit

AUDIT TRAIL			
No.	On	Audit	Remarks
1	29 Apr 2022 13:34	Clm Veh Model Changed	
2	29 Apr 2022 13:34	Clm Created	Reg No: SNC3726M. Policy No: 7210123870. Acct Date: 2022/04/28. Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R224S0001
3	04 May 2022 13:06	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.
4	04 May 2022 13:06	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)
5	04 May 2022 13:06	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):
6	04 May 2022 13:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/05/13
7	04 May 2022 13:06	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.
8	04 May 2022 13:06	Clm Registration Modified	Rep:1137->200611.
9	04 May 2022 13:06	Clm Veh Model Changed	(206863) AUDI A4 2.0 TFSI S-TRONIC (A).
10	04 May 2022 13:08	Adj Adjuster Assigned	[None] -> ADRIAN LING
11	05 May 2022 12:47	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 100.00. Excess Waived: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.
12	05 May 2022 16:37	Adj Rpt Initiated	
13	05 May 2022 16:37	Clm Dtl Modified	Claim Conclusion: -> 3.
14	05 May 2022 16:37	Clm Dtl Modified	JPJ Reg. Date: -> 2021/10/15.
15	05 May 2022 16:37	Clm Details Notified	
16	05 May 2022 17:35	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/05/13

[] Merimen Administrator

[I] Merimen Administrator

[] CELINE FONG

[] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[I] Loo, Tong Shing

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] SHIAU CHAN

AUDIT TRAIL

No.	On Audit	Remarks	By
17	05 May 2022 17:36 Adj Mandate Request	Cur.Req:94748.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. (BASED ON NEW FOR OLD) WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	06 May 2022 17:02 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/05/13. Mandate Remarks: Vehicle may commence repair - Repair Limit to set @ \$95K. (Potential Recovery) Checked and Supplementary items to resurvey with CLEAR damaged photos. Before paint photos required to be done	[I] Lim, Kok-Chong
19	06 May 2022 17:03 Adj Mandate Set	Approved:78119.00:Vehicle may commence repair - Repair Limit to set @ \$95K. (Potential Recovery) Checked and Supplementary items to resurvey with CLEAR damaged photos. Before paint photos required to be documented in Merimen.Reinsp:Yes.	[I] Lim, Kok-Chong
20	17 May 2022 12:06 Cim Dtl Modified	Driver Name: LEE SZE YI ANDY -> LIM SZE YI ANDY.	[A] CELINE FONG
21	03 Jun 2022 15:16 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/05/13	[A] SHIAU CHAN
22	03 Jun 2022 15:16 Adj Mandate Request	Cur.Req:99372.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
23	06 Jun 2022 14:08 Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/05/13. Mandate Remarks: Repair Limit to set @ \$95K. (Potential Recovery) Checked and Supplementary items to resurvey with CLEAR damaged photos. Before paint photos required to be documented in Merimen.	[I] Lim, Kok-Chong
24	06 Jun 2022 14:08 Adj Mandate Set	Approved:85251.00:Repair Limit to set @ \$95K. (Potential Recovery) Checked and Supplementary items to resurvey with CLEAR damaged photos. Before paint photos required to be documented in Merimen.	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2789589	05 May 2022 16:37:38	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SNC3726M		11.00