



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22004098/y3	
			Date: 04/05/2022	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SLR 9750Y	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	500.00	
	Assign From JOSEPHINE WONG	Assign Date	04/05/2022	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 29/04/2022	Inspection Date		
	Survey held at SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			