

ESTIMATE OF REPAIR

Veh# : GBF3433J

Accident Date : 30/4/2022

Location : BUKIT BATOK WEST AVE 6 BLK 118 CARPARK

TP Ergo.

Hui Rong.

Model: TOYOTA HIACE
(21/9/2016)

3P: XE3360E (ERGO)

TRFHT02PX00205887

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear o/s bumper top garnish <i>Repair</i>	80.60	+	
2	1 pc	Rear tail-gate <i>Distorted</i>	1,825.90	1755	
3	1 pc	Rear tail-gate weatherstrip <i>He m</i>	320.00	+	
4	1 pc	Rear tail-gate 'TOYOTA' emblem <i>He m</i>	82.00	SS	
5	1 pc	Rear tail-gate '70 KMPH' emblem <i>He m</i>		15.00	✓
6	1 pc	Rear tail-gate '10 PAX' emblem <i>He m</i>		15.00	✓
7	1 pc	Rear tail-gate 'TOYOTA HIACE' emblem <i>He m</i>	60.00	-	
8	1 pc	Rear o/s tail lamp <i>cracked</i>	420.20	345	
9	1 pc	Rear o/s tail lamp panel <i>Repair</i>	325.00	+	
10	1 pc	Rear n/s body panel silding guide <i>He m</i>	420.40	+	
11	1 pc	Rear n/s body panel <i>Distorted</i>	1,867.80	✓	
12	1 pc	Rear windscreen moulding <i>He m</i>		120.00	✓
13	1 pc	Rear windscreen sealant <i>He m</i>		80.00	60
		4082.80 Sub-Total:	5,401.90	230.00	0.00
		3062.10 SW: 210	25%	0%	10%
		After Less %:	4,051.43	230.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.	1,400.00	600	
2		To spray painting.	800.00	500	
3		To remove & refit rear windscreen	140.00	120	
4		To remove and refit rear reverse camera	50.00	✓	
5		To remove and refit rear upholstery to facilitate repair	150.00	60	
6		To check wiring.	80.00	30	
7		To re-seal anti-rust.	50.00	✓	
8		To check and reset electrical system	80.00	x	
		Sub-Total:	2,750.00		
		Total:	7,031.43		
		After less 20%:	5,625.14		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Chan San Choo
Director
DipEng, AAE MIM MSAE(A) Rep

Signature:

