

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI22004135/Uqcn2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Da	ate: 30/05/2022	
			Co	ode: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMT 1715E	Veh. Inspected	SFU 5666P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10015050/CD	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	04/05/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 6 (A)	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JM6GJ1072G0204429	Colour	SILVER	
	Odometer	91511 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/55 ZR17	KAPSEN	6 mm	
	L/H Front Tyre	225/55 ZR17	KAPSEN	6 mm	
	R/H Rear Tyre	225/55 ZR17	KAPSEN	6 mm	
	L/H Rear Tyre	225/55 ZR17	KAPSEN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	01/05/2022	Inspection Date	04/05/2022	
	Survey held at	TAN LIM MOTOR PTE LTD			
		NO.1 DEFU LANE 6 SINGAPORE 539365			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: