

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB7889D (Insd veh)	Model:	TOYOTA HARRIER 2.0
	SJX3092U (TP veh)		ELEGANCE (A)
Date of Accident:	04/05/2022		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		10,783.57
Final Repair Cost	:	\$		3,745.00
Loss of Use	:	\$		400.00
				4.00 days at \$100.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		4,147.00

Is Third Party Workshop GIA Registered?				[] YES	[X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	: \$	4,147.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

15 Aug
2022

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))