



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH		Ref: CC4/ASM22004148/Upa3q2 Date: 17/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3537Z	Veh. Inspected	GBB 2696U
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M0402X	Excess (\$)	0.00
Assign From		Assign Date	05/05/2022
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR (M)	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JN1SC2F24Z0800674	Colour	SILVER
Odometer	193870 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	MAXTREK	6 mm
L/H Front Tyre	195 R15	MAXTREK	6 mm
R/H Rear Tyre	155 R13 (D)	FALKEN	6/6 mm
L/H Rear Tyre	155 R13 (D)	FALKEN	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/05/2022	Inspection Date	05/05/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	