

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Tuesday, 13 September 2022 6:07 PM  
**To:** ENG HUEY NI  
**Cc:** MT\_Claim\_SG; Admin A  
**Subject:** [SEEK MANDATE] - Your ref: 22/22/22/VC05/025732 // Our ref : CC4/LPC22004153/Kpa3q2 [ACCIDENT INVOLVING GBB7796G (LONPAC) / GBF3118U(TP) / FK1254Z ON 27/04/2022]  
**Attachments:** LKK Survey Report & Photos.pdf; TP LOD & Docs.pdf

Your ref: **22/22/22/VC05/025732**  
Our ref : CC4/LPC22004153/Kpa3q2

Dear Sirs/Mdm,

### **ACCIDENT INVOLVING GBB7796G (LONPAC) / GBF3118U(TP) / FK1254Z ON 27/04/2022**

We refer to the above matter.

The accident occurred when our insured driver moved forward and collided onto third party parked vehicle(GBF3118U). The impact caused third party hit onto a parked motorbike(FZ1254Z). We are of the view that liability is not in our driver' favour.

We seek your approval to offer repairer "**LIM TAN MOTOR PTE LTD**" at **\$5,967.95(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 9,926.84	\$ 5,510.50 (\$5,150.00 + 7%GST)
2. Loss of Rental (3days x \$150.00)	\$ 450.00	\$ 450.00 (3days x \$150.00)
3. LTA/GIA Search Fee	\$ 7.45	\$ 7.45
<b>Total</b>	<b>\$10,384.29</b>	<b><u>\$ 5,967.95</u></b>

Surveyor recommended 6days for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 26/08/2022 is only for mandate purpose.

**Kindly let us have your approval / instruction.**

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |  
S(408933)