



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22004155/Avcn2 Date: 06/06/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGJ 7161L	Veh. Inspected	SML 3050T	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10015000/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	05/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ACR500102771	Colour	WHITE	
Odometer	176483 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	TOYO	6 mm	
L/H Front Tyre	225/50 R18	TOYO	6 mm	
R/H Rear Tyre	225/50 R18	TOYO	6 mm	
L/H Rear Tyre	225/50 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/04/2022	Inspection Date	05/05/2022	
Survey held at	AUTOBACS CAR CARE (SINGAPORE) PTE LTD 8 KAKI BUKIT AVE 4 #08-40/45/46 PREMIER @KAKI BUKIT S (415875)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	