



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897		Ref: CS/AIS22004161/Eqce2 Date: 02/06/2022 Code: AIS	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLZ 746C
Policy No.	SP2001255858-01	Coverage (\$)	0.00
Claim No.	2022 22004739SL	Excess (\$)	700.00
Assign From	SHANTI	Assign Date	05/05/2022
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I30	c.c	1353
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	TMAH3513VJJ064981	Colour	GREY
Odometer	67986 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40Z R18	MICHELIN	4 mm
L/H Front Tyre	225/40Z R18	MICHELIN	4 mm
R/H Rear Tyre	225/40Z R18	MICHELIN	4 mm
L/H Rear Tyre	225/40Z R18	MICHELIN	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/04/2022	Inspection Date	06/05/2022
Survey held at	KOMOCO MOTORS PTE LTD 253 ALEXANDRA ROAD #01-01 SINGAPORE 159936.		
5a. Remarks			
A)THE MARKET VALUE IS S\$73,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	