



HYUNDAI

KOMODO MOTORS PTE LTD

231 Avenida Rio Vista, Singapore 110098
Tel: 65 6472 5288 Fax: 65 6472 1463 www.komodo.com.sg
GST No: T190558K

(GST REGISTRATION NO: MR-8500364-4)

Date: 4/5/2022
11 MAR 2022

ALLIANZ Insurance Singapore Pte Ltd
Attn: Motor Claims Department

Vehicle number : SLZ 746 C
Make and model : I30 1.4 GLS 5DR DCT TURBO
Registration Date : 23/04/2018
Chassis number : TMAH3513VJJ064981
Engine number : G4LDHD120582

Job No. :
Owner name : Tan Jing Felix
Date of Acc : 29/04/2022
Policy number : SP2001255858-01
Claim Type : OD-Excess TBC

Items : Estimate

Items	Part Description	Part No.	Unit	Estimate	Remarks
1	BUMPER CLIP X10	86595-2T500	\$	12.00	rec
2	UPPER GRILLE CLIP X6	14206-08250B	\$	3.60	rec
3	GRILLE-RADIATOR	86351-G4010	\$	480.20	BR
4	CR PIECE 1-RADIATOR GRILLE	86355-G4100	\$	255.90	BR
5	STRIP ASSY-FR BUMPER UPR	86357-G4000	\$	64.89	CRU 68.30
6	EMBLEM-SYMBOL MARK	86300-G4100	\$	26.10	BR
7	COVER-RADIATOR GRILLE,UPR	86362-G4000	\$	150.44	CRU 158.60
8	COVER-FR BUMPER	86511-G4000	\$	838.64	939.70
9	GRILLE-FRONT BUMPER	86561-G4000	\$	123.41	BR
10	BRACKET-FR BUMPER SIDE,LH	86513-G4000	\$	74.93	? / BR 78.80
11	BRACKET-FR BUMPER SIDE,RH	86514-G4000	\$	74.93	? x nn
12	MOULDING-FRT BPR LICENSE PLATE	86519-G4000	\$	41.83	BR 44.20
13	ABSORBER-FRONT BUMPER ENERGY	86520-G4050	\$	224.91	? BR
14	COVER-FR BUMPER FOG LAMP,LH	86563-G4040	\$	88.99	? BR 93.60
15	COVER-FR BUMPER FOG LAMP,RH	86564-G4040	\$	88.99	x nn
16	BRACKET-FRT BUMPER MOUNTING,LH	86553-G4000	\$	44.75	? BR 47.90
17	BRACKET ASSY-FR BUMPER UPR SUP X2	86556-F2000	\$	16.80	? BR 8.40
18	BRACKET-FRT BUMPER MOUNTING,RH	86554-G4000	\$	44.75	? x nn
19	PIECE-RADIATOR GRILLE NO.2	86353-G4000	\$	158.30	? BR 162.90
20	PIECE-RADIATOR GRILLE NO.3	86354-G4000	\$	112.86	? x nn
21	GARNISH-RADIATOR GRILLE,UPR	86356-G4000	\$	73.90	BR 77.80
22	DUCT ASSY-AIR CURTAIN,LH	86567-G4030	\$	47.68	? x nn
23	DUCT ASSY-AIR CURTAIN,RH	86568-G4030	\$	47.68	x nn
24	STIFFNER-FR BPR LWR	86571-G4000	\$	174.25	x nn
25	CAP ASSY-FR BPR	86588-G4000	\$	24.84	x nn
26	LIP ASSY-FRONT BUMPER	86591-G4000	\$	161.80	? x nn
27	LAMP ASSY-FRONT FOG,LH	92201-G4000	\$	265.10	x nn
28	LAMP ASSY-FRONT FOG,RH	92202-G4000	\$	265.10	x nn
29	LAMP ASSY-DAY RUNNING LIGHT,LH	92207-G4100	\$	642.50	? x nn
30	LAMP ASSY-DAY RUNNING LIGHT,RH	92208-G4100	\$	642.50	x nn

Vehicle number : SLZ 746 C
 Make and model : I30 1.4 GLS 5DR DCT TURBO
 Registration Date : 23/04/2018
 Chassis number : TMAH3513VJJ064981
 Engine number : G4LDHD120582

Job No. :
 Owner name : Tan Jing Felix
 Date of Acc : 29/04/2022
 Policy number : SP2001255858-01
 Claim Type : OD-Excess TBC

Items :	Estimate
31 LAMP ASSY-HEAD,LH <i>OR</i>	92101-G4030 \$ 1,686.80 ✓
32 LAMP ASSY-HEAD,RH <i>? X nn</i>	92102-G4030 \$ 1,686.80
33 BEAM COMPLETE-FR BUMPER <i>M</i>	64900-G4000 \$ 636.40 ✓
34 CARRIER ASSY-FRONT END MODULE <i>OR</i>	64101-G4000 \$ 1,332.76 ✓
35 HORN ASSY-LOW PITCH <i>X nn</i>	96610-G3000 \$ 73.50
36 PANEL ASSY-HOOD <i>OD</i>	66400-G4000 \$ 1,502.54 ✓
37 HINGE ASSY-HOOD,LH <i>GT</i>	79110-G3000 \$ 49.50 ✓
38 HINGE ASSY-HOOD,RH <i>GT</i>	79120-G3000 \$ 49.50 ✓
39 PAD-HOOD INSULATING <i>CRU</i>	81125-G4000 \$ 419.30 <i>422.70</i>
40 LATCH ASSY-HOOD <i>? BT</i>	81130-G3900 \$ 114.80 ✓
41 CABLE ASSY-HOOD LATCH RELEASE <i>X nn</i>	81190-G3800 \$ 12.40
42 SIDE BUMPER-HOOD OVERSLAM X2 <i>X nn</i>	17372-09520B \$ 2.00
43 FRT BUMPER-HOOD OVERSLAM X2 <i>X nn</i>	17377-22036B \$ 7.60
44 COVER ASSY-COWL TOP SIDE,LH <i>CRU</i>	86152-G4000 \$ 73.04 <i>76.80</i>
45 COVER ASSY-COWL TOP SIDE,RH <i>CRU</i>	86153-G4000 \$ 136.55 <i>140.40</i>
46 COVER ASSY-COWL TOP <i>X nn</i>	86150-G4900 \$ 683.22
47 RETAINER-COWL TOP COVER MTG X4 <i>REC</i>	86155-2H100 \$ 5.60
48 PANEL ASSY-FENDER,LH <i>OD</i>	66310-G3000 \$ 1,061.90 ✓
49 PANEL ASSY-FENDER,RH <i>X nn</i>	66320-G3000 \$ 1,061.90
50 FILLER NECK ASSY-RADIATOR <i>? X nn</i>	25329-F3300 \$ 28.80
51 BLOWER ASSY <i>? X nn</i>	25380-F3300 \$ 567.50
52 HOSE-RADIATOR INLET <i>? X nn</i>	25411-F2250 \$ 48.10
53 HOSE ASSY-RADIATOR,UPR <i>? X nn</i>	25414-F3300 \$ 42.40
54 HOSE ASSY-RADAATOR,LWR <i>? X nn</i>	25415-F3300 \$ 59.10
55 GUARD-AIR,LH <i>CRU</i>	29136-G4200 \$ 73.04 <i>76.80</i>
56 GUARD-AIR,RH <i>CRU</i>	29134-G4200 \$ 73.04 <i>76.80</i>
57 CONDENSER ASSY-COOLER <i>OD</i>	97606-F2200 \$ 745.10 ✓
58 RADIATOR ASSY <i>? BT</i>	25310-G4300 \$ 1,009.69 ✓
59 ANTIFREEZER <i>? REC</i>	99H94-AQ710H \$ 95.60 ✓
60 AIR GUIDE-INTERCOOLER <i>? X nn</i>	28272-2A690 \$ 31.00
61 COOLER ASSY-INTER <i>? X nn</i>	28270-03110 \$ 915.40
62 DUCT ASSY-EXTENSION <i>? X nn</i>	28220-G3000 \$ 143.20
63 DUCT-EXTENSION <i>? X nn</i>	28212-G3000 \$ 3.50
64 SHIELD-AIR INTAKE <i>? X nn</i>	28213-G3000 \$ 8.60
65 DUCT-AIR "B" <i>? X nn</i>	28210-G3000 \$ 96.80
66 RETAINER-COWL TOP COVER MTG X2 <i>REC</i>	86155-2H100 \$ 2.80 ✓
67 WIRING ASSY-BATTERY <i>? X nn</i>	91850-G4490 \$ 1,239.41
68 WIRING ASSY-FEM <i>? X nn</i>	91870-G4060 \$ 236.16
69 WIRING ASSY-FRT <i>? X nn</i>	91228-G4631 \$ 7,187.25
70 WIRING ASSY-CONTROL <i>? X nn</i>	91420-G4010 \$ 3,738.61
	<u>\$ 32,211.78</u>
Less 20% Discount	\$ 6,442.36
Material total	<u>\$ 25,769.42</u>

Vehicle number : **SLZ 746 C**
 Make and model : I30 1.4 GLS 5DR DCT TURBO
 Registration Date : 23/04/2018
 Chassis number : TMAH3513VJJ064981
 Engine number : G4LDHD120582

Job No. :
 Owner name : Tan Jing Felix
 Date of Acc : 29/04/2022
 Policy number : SP2001255858-01
 Claim Type : OD-Excess TBC

Body, Paint & Labour Items :	Estimate
1 To carry out accident body repair 380 x 4	\$ 3,040.00 1520 /
2 Complete putty and spray paint all affected areas 340 x 4	\$ 2,040.00 1360 /

Labour Charges:	Estimate
3 TO REFOCUS BOTH FRT HEAD LAMP (S.NETT)	\$ 40.00 /
4 TO SUPPLY BONNET SEALANT (S.NETT)	\$ 100.00 /
5 TO VACUUM & TOP UP AIRCON GAS (S.NETT)	\$ 140.00 /
6 TO SUPPLY & INSTALL FRT NUMBER PLATE (S.NETT)	\$ 40.00 / OR
7 TO REPAIR CHASSIS MEMBER (S.NETT)	\$ 320.00 8 /
8 TO PUT ON CHASSIS BENCH ALIGNER	\$ 320.00 7 /
9 TO R&I DASHBOARD ASSY TO FACILITATE REPAIR (S.NETT)	\$ 570.00 7 /
10 TO RENEW FRT WIRING ASSY & REPROGRAM (S.NETT)	\$ 570.00 7 /
11 TO RENEW CONTROL WIRING ASSY & REPROGRAM (S.NETT)	\$ 570.00 7 /
12 TO RENEW BATTERY / FEM WIRING & REPROGRAM (S.NETT)	\$ 380.00 1 /
Total	\$ 33,840.62
Excess	
Add GST 7%	

Grand Total

*** Estimation are base on visual inspection, should there be further damages found during process of repair, you will be inform prior before carry out***

Store CLKK) OD-M KL
 6/5/22, 10:00am EXCESS-?
 PIP
 My Reply
 8 days

LKR Auto Centre (P) Ltd. hereby certify
 the Repairer of this vehicle to be:
 • To resurvey before and after repair
 • To display damaged parts
 • Parts prices are subject to
 • Third party survey to be a fair and reasonable price
 • No illegal modification of a vehicle
 • Supplementary items must be approved
 is subject to final approval from insurer's surveyor

Acknowledged by Repairer
 Signature:
 Date: