

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3063/04/22

Your Ref: _____

Date: 21st April 2022

MR HO KUM CHUEN
BLK 648, #10-3351
ANG MO KIO AVE 5,
SINGAPORE 560648

Not Actual
her
1/s \$1700
4 days
25/4/22
take the the rep.

Estimate cost of repair to HYUNDAI AVANTE 1.6 (A) Saloon - SJR 5067 L

1 pc rear bumper		\$	498.00	—
10 pcs rear bumper clips	@ \$ 3.50		35.00	—
1 pc rear bumper o/s side retainer			29.00	—
3 pcs rear bumper o/s inner shield clips	@ \$ 3.50		10.50	X
1 pc rear o/s fender			1,806.00	X
6 pcs rear o/s fender inner shield clips	@ \$ 3.50		21.00	X
1 pc rear o/s door			1,743.00	X
16 pcs rear o/s door inner trim board clips	@ \$ 5.50		88.00	X
1 pc rear o/s lower arm			239.00	X
1 pc rear o/s shock absorber shaft			232.00	X
1 set rear o/s wheel bearing & hub			395.00	X
		\$	5,096.50	
	Less 20%	\$	1,019.30	
		\$	4,077.20	
1 pc rear o/s sport rim		\$	650.00	S.N
1 pc rear o/s wheel tyre (195X65XR15)		\$	400.00	S.N
To wiring check up for affected wiring system.			50.00	20
To check & adjust wheel balancing & wheel alignment.			150.00	60
To remove & refix rear o/s shock absorber shaft, lower arm, wheel bearing & necessary parts.			220.00	X
To remove & refix carpet, floor mat, rear o/s fender inner garnish, rear o/s door inner trim board cover for repair.			180.00	60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s door & necessary parts, to weld, renew & align above parts.			1,350.00	450
To putty & respray painting on all affected accident parts.			1,500.00	600
To respray Tuff-Kote on all affected accident parts.			80.00	X
		\$	8,657.20	

Dollars : Eight Thousand Six Hundred Fifty Seven And Cents Twenty Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-562
202
469.60
2139.6
202
1711