



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN		Ref: CC4/ASM22004167/Uga3q2 Date: 30/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SGX 4258M	<b>Veh. Inspected</b>	SJR 5378P
<b>Policy No.</b>	GA249114	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M0403M	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	05/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	TOYOTA WISH (A)	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	ZGE200008265	<b>Colour</b>	WHITE
<b>Odometer</b>	120170 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/45 R17	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	215/45 R17	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	215/45 R17	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	215/45 R17	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.		
<b>5. General Information</b>			
<b>Accident Date</b>	04/05/2022	<b>Inspection Date</b>	06/05/2022
<b>Survey held at</b>	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
<b>5b. Estimate Days of Repair</b>			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>