

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Telma Gomez

Date: 10 Aug 2022

Preliminary Advice

Insured	: SLP176A		
Vehicle No			
TP Vehicle No	: SH8046Z	Accident Date	: 28/04/2022
Make	: HYUNDAI IONIQ HYBRID	Assignment Date	: 05/05/2022
Date of Inspection	: 06/05/2022	Est. Duration of Repair	: 3
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,452.84
Revised Amount	:S\$	2,317.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,317.72

Lump Sum Repair	:S\$	1,800.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.