

**SERVICE ESTIMATE**

##### - C00001 SL: SERVICE SALES - PC  
 Ms Alexia Ho Wen Tsi  
 522 East Coast Road #17-01

GST Reg.No:M28920628X  
 0 Page 1

Singapore 458966

Inv.No. . : B&P  
 Inv.date. : 05/05/2022  
 WIP No. . : 23674  
 Veh.In/Out:  
 \*Tel.No. . : Mobile: 98164184  
 Reg.No. . : SBV68R  
 Reg.date . : 30/10/2020  
 Mileage . : 0  
 Chassis No: SADCA2AXXKA616467

Closed by . . . : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks . . . . : Ms Alexia Ho Wen Tsi

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR TOW HOOK COVER, REINFORCEMENT, ETC	0	1500.00	0	1300	1,500.00	S
800	TO SPRAY REAR BUMPER, REINFORC ETC	0	1800.00	0	1000	1,800.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0	/	621.00	S
	COVER-BUMPER REAR / <i>DD</i>	1.0 EA	1957.80	1762.02		1,957.80	S
	MOUNTING-BRACKET CTR / <i>CVT</i>	1.0 EA	234.30	210.87		234.30	S
	BUMPER NUT XF / <i>APC</i>	10.0 EA	5.30	47.70		53.00	S
	COVER-TWNG HK OPNNG / <i>CR4</i>	1.0 EA	33.40	30.06		33.40	S
	PANEL VALANCE <i>X 111</i>	1.0 EA	257.30			257.30	S
	BUMPER BEAM REAR XE <i>X 111</i>	1.0 EA	714.30			714.30	S
	SENSOR / <i>CVT</i>	1.0 EA	428.10	385.29		1,712.40	S
	LAMP-FOG LH <i>X 111</i>	1.0 EA	340.80			340.80	S
	ANTENNA <i>X 111</i>	1.0 EA	43.80			43.80	S

SINGAPORE

**SERVICE ESTIMATE**

##### - C00001 SL: SERVICE SALES - PC  
 Ms Alexia Ho Wen Tsi  
 522 East Coast Road #17-01

GST Reg.No:M28920628X  
 0 Page 2

Singapore 458966

Inv.No. . . : B&P  
 Inv.date. . : 05/05/2022  
 WIP No. . . : 23674  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98164184  
 Reg.No. . . : SBV68R  
 Reg.date . . : 30/10/2020  
 Mileage . . : 0  
 Chassis No: SADCA2AXXKA616467

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Ms Alexia Ho Wen Tsi

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HEATSHIELD LH X no	1.0 EA	81.50			81.50	S
	HEATSHIELD LH X no	1.0 EA	62.80			62.80	S

*Stere (LKK) over R  
 11/5/22, 11.2k  
 P/P  
 3 d/s*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Labour Total	3,921.00
Parts Total	5,491.40
Package Total	0.00

Gross Total.	9,412.40
Net.....	9,412.40
GST @ 7.0%	658.87
Total.....	10,071.25
Paid.....	0.00
Please Pay..	10,071.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated