



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22004201/Kny3e2 Date: 11/08/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SFB 6883Y
	Policy No.	Z21VP05029819	Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025742	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	06/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200 (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDD2130422A027556	Colour	METALLIC BLACK
	Odometer	99629 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R18	PIRELLI	7 mm
	L/H Front Tyre	245/45 R18	PIRELLI	7 mm
	R/H Rear Tyre	275/40 R18	PIRELLI	7 mm
	L/H Rear Tyre	275/40 R18	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/05/2022	Inspection Date	06/05/2022
	Survey held at	CHENG HOE MOTOR SERVICE 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047		
5a. Remarks				
	A)THE MARKET VALUE IS S\$123,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	