

ASS. REC. BY:

REF:

LPC /

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.8.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFB 68834

Yr Regn:

09, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer E200

c.c

1991

Colour

m. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

9982P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2130422A 027556

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

245/45R18

R:

275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/5/22

D.O.I.

6/5/2022

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rt N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

*Not Notarish  
B4 Point*

M/S : LONPAC INSURANCE BERHAD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

Claim No: ES2290446

Estimate No: ES2290446/YISHUN

Date: 06 May 2022

Policy No: Z21VP05029819

Veh Reg No: SFB6883Y

Make/Model: MERCEDES MERC  
BENZ E200 EXCLUSIVE  
(R18 LED)

Chassis No: WDD2130422A027556

Engine No: 27492030690197

Reg. Date: 15/09/2016

WS Ref: OD/LONPAC

Claim Type: Own Damage

Accident Date: 02/05/2022

## Estimate Repair Cost to Vehicle No : SFB6883Y

| Description                                                                                                                             | U/Price  | Quantity | Cost      | Amount   |
|-----------------------------------------------------------------------------------------------------------------------------------------|----------|----------|-----------|----------|
|                                                                                                                                         |          |          | SS        | SS       |
| <b>Cost Plus</b>                                                                                                                        |          |          |           |          |
| 1 FRONT BUMPER                                                                                                                          | 810.00   | 1 PC     | 810.00    | ✓        |
| 2 FRONT BUMPER REINFORCEMENT                                                                                                            | 280.00   | 1 PC     | 280.00    | ✓        |
| 3 FRONT BUMPER SPONGE <i>Fog lamp</i>                                                                                                   | 95.00    | 1 PC     | 95.00     | ✓        |
| 4 FRONT BUMPER LH HEADLAMP COVER                                                                                                        | 55.00    | 1 PC     | 55.00     | ✓        |
| 5 FRONT BUMPER LH FOG LAMP COVER CHROME                                                                                                 | 45.00    | 1 PC     | 45.00     | ✓        |
| 6 FRONT BUMPER LH OUTER PDC SENSOR                                                                                                      | 115.00   | 1 PC     | 115.00    | ✓        |
| 7 FRONT BUMPER LH CORNAL PARKING SENSOR                                                                                                 | 115.00   | 1 PC     | 115.00    | ✓        |
| 8 FRONT BUMPER LH SIDE INNER FRAME                                                                                                      | 55.00    | 1 PC     | 55.00     | ✓        |
| 9 FRONT BUMPER RIVET PIN                                                                                                                | 5.00     | 12 PC    | 60.00     | ✓        |
| 10 FRONT BUMPER PDC SENSOR WIRE HARNESS                                                                                                 | 275.00   | 1 SET    | 275.00    | ✓        |
| 11 FRONT GRILLE ASSY                                                                                                                    | 520.00   | 1 PC     | 520.00    | ✓        |
| 12 BONNET                                                                                                                               | 1,350.00 | 1 PC     | 1,350.00  | ✓        |
| 13 BONNET LH UPPER LATCH                                                                                                                | 50.00    | 1 PC     | 50.00     | ✓        |
| 14 BONNET LH INNER LOCK                                                                                                                 | 60.00    | 1 PC     | 60.00     | ✓        |
| 15 BONNET SPRING ELEMENT                                                                                                                | 24.00    | 2 PC     | 48.00     | ✓        |
| 16 FRONT LH FENDER                                                                                                                      | 590.00   | 1 PC     | 590.00    | ✓        |
| 17 FRONT LH FENDER EXPANSION RIVETS                                                                                                     | 4.00     | 4 PC     | 16.00     | ✓        |
| 18 FRT SUPPORT PANEL                                                                                                                    | 520.00   | 1 PC     | 520.00    | ✓        |
| 19 FRONT MOUNTING CONSOLE                                                                                                               | 140.00   | 1 PC     | 140.00    | ✓        |
| 20 HEADLAMP LH                                                                                                                          | 1,720.00 | 1 PC     | 1,720.00  | ✓        |
| 21 HEADLAMP LH CONTROL UNIT                                                                                                             | 410.00   | 1 PC     | 410.00    | ✓        |
|                                                                                                                                         |          |          | 7,329.00  |          |
|                                                                                                                                         |          |          | 1,099.35  | 8,428.35 |
| <b>Labour</b>                                                                                                                           |          |          |           |          |
| 22 REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, BONNET & ATTACHMENTS, HEADLAMP, FRT LH FENDER, FRT SUPPORT PANEL & REALIGN THE SAME | 800.00   | 1 LA     | 800.00    | 500      |
| 23 PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS, BONNET, FRT LH FENDER & ALL AFFECTED AREAS                                             | 700.00   | 1 LA     | 700.00    | 600      |
| 24 REMOVE & REFIX PARKING SENSORS, CHECK RESET THE SAME                                                                                 | 80.00    | 1 LA     | 80.00     | 60       |
| 25 REMOVE & REFIX HEADLAMP CONTROL UNIT, REPROGRAMME & RESET THE SAME                                                                   | 180.00   | 1 LA     | 180.00    | 120      |
|                                                                                                                                         |          |          | 10,188.35 |          |

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**

OneMotoring

## Inquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 595I

## Vehicle Details

Vehicle No.: SFB6883Y  
Vehicle to be Exported: No  
Intended Deregistration Date: 04 May 2022  
Vehicle Make: MERCEDES BENZ  
Vehicle Model: E200 EXCLUSIVE (R18 LED)  
Primary Colour: Black  
Manufacturing Year: 2016  
Engine No.: 27492030690197  
Chassis No.: WDD2130422A027556  
Maximum Power Output: 135.0 kW (181 bhp)  
Open Market Value: \$54,238.00  
Original Registration Date: 15 Sep 2016  
First Registration Date: 15 Sep 2016  
Transfer Count: 0  
Actual ARF Paid: \$69,629.00

## Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 14 Sep 2026  
PARF Rebate Amount: \$48,740.00

## Intended COE Rebate Details

COE Expiry Date: 14 Sep 2026  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$57,903.00  
COE Rebate Amount: \$25,252.00  
Total Rebate Amount: \$73,992.00

The information contained herein is correct as at 04 May 2022

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 04/05/2022 18:06 (SGT)  
Date of Accident ..... 02/05/2022 02:30 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... KITCHENER ROAD  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SFB6883Y

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... LYE YOON SAN  
NRIC No ..... SXXXX595I  
Email Address ..... jameslye61@gmail.com  
Mobile Phone No ..... (Phone) +65-96956883  
Alternative Phone No ..... +65-96956883

### VEHICLE PARTICULARS


Manufacturer ..... Mercedes  
Model ..... E200 EXCLUSIVE (R18 LED)  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1991

### INSURANCE COMPANY

Name of Insurance Company ..... Lonpac Insurance Bhd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... Z21VP05029819  
Cover Note Number ..... 15/09/21 - 14/09/22

### DRIVER

Name of Driver ..... LYE YOON SAN  
NRIC No ..... SXXXX595I



A = SFB 6883 Y  
 B = SMP 9835 K  
 Goh Pei Zong  
 S9115549 D

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

I was unable to brake in time and hit onto the rear of car B. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

☒ Claim Own Policy    ☐ Claim Third Party    ☐ Reporting Only  
☐ Claim OD/TP at other workshop ( )