

ASS. REC. BY:

REF:

LPC / 22004201/KHY3

ASSIGNMENT

C

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$123K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.8.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFB 6834

Yr Regn:

09, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer E200

c.c.

1991

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

9982P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2130422A 027556

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

245/45R18

R:

275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/5/22

D.O.I.

6/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/7 88730.85 Car

(Red, \$1457.50, 1490)

Date/Time, File Pass to?

☐

: Prell. Report

1) 3/8/22

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

OD

Lump Sum / I.B.I. (\$

8730.85

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 595I

Vehicle Details

Vehicle No.: SFB6883Y
Vehicle to be Exported: No
Intended Deregistration Date: 04 May 2022
Vehicle Make: MERCEDES BENZ
Vehicle Model: E200 EXCLUSIVE (R18 LED)
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: 27492030690197
Chassis No.: WDD2130422A027556
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$54,238.00
Original Registration Date: 15 Sep 2016
First Registration Date: 15 Sep 2016
Transfer Count: 0
Actual ARF Paid: \$69,629.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Sep 2026
PARF Rebate Amount: \$48,740.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$57,903.00
COE Rebate Amount: \$25,252.00
Total Rebate Amount: \$73,992.00

The information contained herein is correct as at 04 May 2022

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : LONPAC INSURANCE BERHAD
 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

Claim No: ES2290446

Estimate No: ES2290446/YISHUN

Date: 06 May 2022

Policy No: Z21VP05029819

Veh Reg No: SFB6883Y

Make/Model: MERCEDES MERC
 BENZ E200 EXCLUSIVE
 (R18 LED)

Chassis No: WDD2130422A027556

Engine No: 27492030690197

Reg. Date: 15/09/2016

WS Ref: OD/LONPAC

Claim Type: Own Damage

Accident Date: 02/05/2022

Estimate Repair Cost to Vehicle No : SFB6883Y

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Cost Plus				
1 FRONT BUMPER	810.00	1 PC	810.00	✓
2 FRONT BUMPER REINFORCEMENT	280.00	1 PC	280.00	✓
3 FRONT BUMPER SPONGE	95.00	1 PC	95.00	✓
4 FRONT BUMPER LH HEADLAMP COVER	55.00	1 PC	55.00	✓
5 FRONT BUMPER LH FOG LAMP COVER CHROME	45.00	1 PC	45.00	✓
6 FRONT BUMPER LH OUTER PDC SENSOR	115.00	1 PC	115.00	✓
7 FRONT BUMPER LH CORNAL PARKING SENSOR	115.00	1 PC	115.00	✓
8 FRONT BUMPER LH SIDE INNER FRAME	55.00	1 PC	55.00	✓
9 FRONT BUMPER RIVET PIN	5.00	12 PC	60.00	✓
10 FRONT BUMPER PDC SENSOR WIRE HARNESS	275.00	1 SET	275.00	✓
11 FRONT GRILLE ASSY	520.00	1 PC	520.00	✓
12 BONNET	1,350.00	1 PC	1,350.00	✓
13 BONNET LH UPPER LATCH	50.00	1 PC	50.00	✓
14 BONNET LH INNER LOCK	60.00	1 PC	60.00	✓
15 BONNET SPRING ELEMENT	24.00	2 PC	48.00	✓
16 FRONT LH FENDER	590.00	1 PC	590.00	600
17 FRONT LH FENDER EXPANSION RIVETS	4.00	4 PC	16.00	✓
18 FRT SUPPORT PANEL	520.00	1 PC	520.00	✓
19 FRONT MOUNTING CONSOLE	140.00	1 PC	140.00	✓
20 HEADLAMP LH	1,720.00	1 PC	1,720.00	✓
21 HEADLAMP LH CONTROL UNIT	410.00	1 PC	410.00	✓
			7,329.00	
			1,099.35	8,428.35
Labour				
22 REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, BONNET & ATTACHMENTS, HEADLAMP, FRT LH FENDER, FRT SUPPORT PANEL & REALIGN THE SAME	800.00	1 LA	800.00	500
23 PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS, BONNET, FRT LH FENDER & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
24 REMOVE & REFIX PARKING SENSORS, CHECK RESET THE SAME	80.00	1 LA	80.00	60
25 REMOVE & REFIX HEADLAMP CONTROL UNIT, REPROGRAMME & RESET THE SAME	180.00	1 LA	180.00	120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

Signature:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : LONPAC INSURANCE BERHAD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

Claim No: ES2290446

Estimate No: ES2290446/YISHUN

Date: 06 May 2022

Policy No: Z21VP05029819

Veh Reg No: SFB6883Y

Make/Model: MERCEDES MERC
BENZ E200 EXCLUSIVE
(R18 LED)

Chassis No: WDD2130422A027556

Engine No: 27492030690197

Reg. Date: 15/09/2016

WS Ref: OD/LONPAC

Claim Type: Own Damage

Accident Date: 02/05/2022

Estimate Repair Cost to Vehicle No : SFB6883Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
				1,760.00
			Total	S\$ 10,188.35
			Add GST @ 7%	713.18
			Total Amount payable	<u>S\$ 10,901.53</u>

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE