

## Celine Fong (LKKAUTO)

**From:** Gan Kwai Leng (Strides Automotive Services Pte Ltd)  
<KwaiLeng.Gan@strides.com.sg>  
**Sent:** Wednesday, 27 April 2022 1:49 PM  
**To:** Admin-D (LKKAUTO)  
**Subject:** RE: PRI; Accident involving SHB 5114S and PEQ6382  
**Attachments:** survey report.pdf

Dear Yan,

Enclosed TP survey report.


Please raise paper survey report soonest possible.

### Third party report & sketch plan

#### Brief Details.

On 01/03/2022 @ about 1736hrs, I was travelling along Turf Club Road heading towards Dunearn Road. I stopped my vehicle at the slip road towards Dunearn Road, waiting for clearance from the incoming traffic.

All of the sudden, I felt an impact from the rear. I alighted from my vehicle and discovered my vehicle was collided from the rear by one taxi. No one was injured and no government property damage. We exchange particulars and left the location. There is no in car camera inside my vehicle, but I believed there is one inside the taxi.




### Our driver report & sketch plan

#### Brief Details.

On the above mentioned date and time, I was driving on the lane Turf club road going into Dunearn road when my vehicle (SHB5114S) collided onto the rear right side of a vehicle (PEQ6382). Both parties are fine and no one sustain any injuries. No one was conveyed to Ambulance and there was no traffic police at scene.

My vehicle (SHB5114S) sustained damages on its left front side and the vehicle that I hit (PEQ6382) suffered slight damages on its back right side.



Thanks & Regards,  
Joey

---

**From:** Meng Yan (LKK Auto) <admin-d@lkkauto.com>  
**Sent:** Monday, 14 March 2022 11:12 am  
**To:** Ong Hua Yen (Strides Automotive Services Pte Ltd) <HuaYen.Ong@strides.com.sg>; 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>  
**Cc:** MTPRI <MTPRI@smrt.com.sg>; Gan Kwai Leng (Strides Automotive Services Pte Ltd) <KwaiLeng.Gan@strides.com.sg>  
**Subject:** RE: PRI; Our Ref: EHA/PEQ6382 Your Ref: SHB 5114S

**CAUTION:** This email originated from outside of SMRT. Do not click links or open attachments unless you recognise the sender and are expecting the content or attachment.

Dear Hua Yen,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

**Note: With immediate effect 04/03/2022 Summer Lee(assignment Team) will no longer be in our company.  
Please contact the undersign for survey arrangement.**

Best Regards,

**Yan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ong Hua Yen (Strides Automotive Services Pte Ltd) <[HuaYen.Ong@strides.com.sg](mailto:HuaYen.Ong@strides.com.sg)>  
**Sent:** Monday, 14 March, 2022 9:21 AM  
**To:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** MTPRI <[MTPRI@smrt.com.sg](mailto:MTPRI@smrt.com.sg)>; Gan Kwai Leng (Strides Automotive Services Pte Ltd) <[KwaiLeng.Gan@strides.com.sg](mailto:KwaiLeng.Gan@strides.com.sg)>  
**Subject:** FW: PRI; Our Ref: EHA/PEQ6382 Your Ref: SHB 5114S

Ref: TAX/03/22/2003

Dear Ms Summer

Kindly survey on “Without Prejudice” basis.

TP: PEQ6382  
Insured: SHB 5114S  
Workshop: Eng Hup Auto Service

Thank you.

Regards,

Hua Yen  
Claim Department

**From:** CINDY KOH <[cindykoh\\_kkcheng@yahoo.com](mailto:cindykoh_kkcheng@yahoo.com)>  
**Sent:** Friday, 11 March 2022 3:26 pm  
**To:** Ong Hua Yen (Strides Automotive Services Pte Ltd) <[HuaYen.Ong@strides.com.sg](mailto:HuaYen.Ong@strides.com.sg)>;  
[Caroline@msfirstcapital.com.sg](mailto:Caroline@msfirstcapital.com.sg)  
**Cc:** MTPRI <[MTPRI@smrt.com.sg](mailto:MTPRI@smrt.com.sg)>; Gan Kwai Leng (Strides Automotive Services Pte Ltd)  
<[KwaiLeng.Gan@strides.com.sg](mailto:KwaiLeng.Gan@strides.com.sg)>  
**Subject:** Re: PRI; Our Ref: EHA/PE 6382 Your Ref: SHB 5114S

**CAUTION:** This email originated from outside of SMRT. Do not click links or open attachments unless you recognise the sender and are expecting the content or attachment.

Our Ref: EHA/PE 6382  
Your Ref: SHB 5114S  
(Please quote our reference number when replying)

11 March 2022

**FIRST CAPITAL INSURANCE PTE LTD**  
Singapore

Dear Sirs

**NOTICE OF ACCIDENT**  
**Claimant: THO WAI YEAP**

***Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident  
occurring on or after 1<sup>st</sup> April 2016 ["Protocol"]***

We refer to your email dated 11 March 2022.

**Firstly**, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 11 March 2022.

**Secondly**, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 11 March 2022.

**Thirdly**, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

**Fourthly, for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.**

**If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.**

**Finally**, the location and contact person of the workshop are as follows:

Name of Workshop	:	<b>Eng Hup Auto Service</b>
Address	:	Blk 1 No. 387J Woodlands Road , Yew Tee Industrial Estate Singapore 677954
Contact person	:	Ah Soon
Telephone No.	:	94235006

REGARDS  
CINDY  
KK CHENG LAW LLC  
DID : 6227 1272