



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Page 1/3
EST Reg. No. 1795011400

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01 068897

ATTN: MOTOR CLAIMS DEPT

Attention : Motor Claim Department

Estimate : ES012387

Date : 06/05/2022

Vehicle Num. : SMR 3550K

Make/Model : HONDA SHUTTLE HYBRID-2018/2019

Chassis/Eng# : GP72001023

Accident Date : 05/05/2022

Claim No. :

Reference : O/D

Policy No. : SP2000519021

*Not Authorize
Manny B. Paim*

*7 days
Ct B2000*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PARTS PURCHASED :

1.	1 PC	FRONT WINDSCREEN GLASS			CM	1,100.00	✓
2.	1 PC	FRONT WINDSCREEN GLASS MOULDING TOP			RM	30.00	✓
3.	1 PC	FRONT WINDSCREEN GLASS MOULDING LOWER			RM	40.00	✓
4.	1 PC	BONNET			RM	600.00	✓
5.	2 PCS	BONNET HINGE	ols ?	nls Dir	35.00	70.00	✓
6.	1 PC	BONNET SEAL			WT	25.00	✓
7.	1 PC	BONNET LOCK			Dir	100.00	✓
X 8.	1 PC	BONNET INSULATOR			Sm	90.00	X
9.	2 PCS 1 PC	FRONT FENDER	ols R	nls Bu	160.00	320.00	✓
10.	1 PC	FRONT WIPER PANEL GARNISH			RM	165.00	✓
X 11.	1 PC	AIR CLEANER DUCT			Sm	48.00	X
X 12.	2 PCS	AIR GUIDE				25.00	X
13.	2 PCS	HEADLAMP		my cm	500.00	1,000.00	✓
X 14.	2 PCS	HEADLAMP CHROME			65.00	130.00	X
15.	2 PCS	HEADLAMP LOWER BRACKET		cm	45.00	90.00	✓
16.	1 PC	RADIATOR SUPPORT PANEL			RM	500.00	✓
17.	1 PC	RADIATOR AUTO				800.00	✓
X 18.	1 PC	RADIATOR FAN GOWLING			cm	75.00	✓
X 19.	1 PC	RADIATOR FAN MOTOR				230.00	X
X 20.	1 PC	RADIATOR FAN BLADE				40.00	X
X 21.	1 PC	RADIATOR HOSE TOP			Sm	30.00	X
22.	1 PC	AIR CON CONDENSER				500.00	✓

PARTS : 6,729.69

+10% 672.90

7,402.65

SN : 159.00

LABOUR 1,840.00

9,401.65

LESS EXCESS - 2,000.00

FINAL 7,401.65

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S1575721 Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 2006 #01-200 S1523840 Tel: 6789-7997 Fax: 6788-7997 No 8 Pandan Loop (Blk 1/Blk K1 S123226) Tel: 6779-5665 Fax: 6779-1110

Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

9139 8600
Mark (owner)

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 068897
ATTN: MOTOR CLAIMS DEPT
Attention : Motor Claim Department

Estimate : ES012387

Date : 06/05/2022
Vehicle Num. : SMR 3550K
Make/Model : HONDA SHUTTLE HYBRID-2018/2019
Chassis/Eng# : GP72001023
Accident Date : 05/05/2022
Claim No. :
Reference : O/D
Policy No. : SP2000519021

S/N	Quantity	Particular	Unit Price	Amount S\$	
23	1PC	RADIATOR SUPPORT PANEL TOP GARNISH		Dis 55.00	✓
X 24	1PC	AIR CON FAN MOTOR		230.00	X
X 25	1PC	AIR CON FAN COWLING		75.00	X
X 26	1PC	AIR CON FAN BLADE		40.00	X
27	1PC	FRONT GRILLE		CM 280.00	✓
28	1PC	FRONT GRILLE LOGO		30.00	✓
X 29	1PC	FRONT GRILLE TOP HOLDER		25.00	X
30	1PC	FRONT BUMPER	650.00	Am 400.00	✓
31	2 PCS	FRONT BUMPER SIDE RETAINER	12.00	DR 24.00	✓
32	1PC	FRONT BUMPER REINFORCEMENT		R 185.00	✓
X 33	1PC	FRONT BUMPER LOWER GRILLE		DR 40.00	✓
X 34	1PC	RH FRONT BUMPER GARNISH		DR 30.00	X
X 35	1PC	OUTSIDE TEMPERATURE SENSOR		70.00	X
36	1PC	LH WIPER GARNISH CORNER		CM 35.00	✓
X 37	2 PCS	HYBRID LOGO	35.00	Am 70.00	✓
Total Parts Purchased S\$:				7,622.00	
10.00% Of The Above Parts S\$:				762.20	
Based On Cost Plus S\$:				8,384.20	
SPECIAL NETT ITEMS :					
1.	1 PC	WINDSCREEN GLASS SEALANT		Am 45.00	✓
2.	1 PC	ERP BRACKET		Am 26.00	✓

CONTINUE / ...



FALCON - AIR

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 068897
ATTN: MOTOR CLAIMS DEPT
Attention: Motor Claim Department

Estimate : ES012387

Date : 06/05/2022
Vehicle Num. : SMR 3550K
Make/Model : HONDA SHUTTLE HYBRID-2018/2019
Chassis/Eng# : GP72001023
Accident Date : 05/05/2022
Claim No. :
Reference : O/D
Policy No. : SP2000519021

S/N	Quantity	Particular	Unit Price	Amount S\$
3.	1 PC	FRONT NUMBER PLATE		45.00 ✓
4.	16 PCS	FRONT BUMPER CLIP	3.00	48.00 ✓
Special Nett Total S\$:				164.00
LABOUR :				
TO CHECK WIRING AND RE-FOCUS HEADLAMP				50.00 201
TO REMOVE/REFIX FRONT WINDSCREEN GLASS				150.00 1201
TO VACUUM, REOIL AND REGAS AIR CON				120.00 1001
TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT CHASSIS, INNER PANEL INCLUDING REPLACEMENT OF PARTS				750.00 6001
TO SPRAY PAINT ON BONNET, BONNET HINGES, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, RADIATOR SUPPORT PANEL, LH/RH FRONT FENDERS				1,600.00 10001
Labour Total S\$:				2,670.00

E. & O.E.

Total S\$: 11,218.20

=====


for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 068897
ATTN: MOTOR CLAIMS DEPT
Attention : Motor Claim Department

Supplementary Estimate : ES012391

Date : 13/05/2022
Vehicle Num. : SMR 3550K
Make/Model : HONDA SHUTTLE HYBRID-2018/2019
Chassis/Eng# : GP72001023
Accident Date : 05/05/2022
Claim No. : 22004767/SL
Reference : O/D
Policy No. : SP2000519021

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	PARTS PURCHASED :		150.00
2.	1 PC	FRONT GRILLE TOP CHROME		110.00
3.	1PC	FRONT GRILLE LOWER CHROME		12.00
4.	1 SET	TOW COVER		18.69
		PRIVATE HIRE DECAL		
		Total Parts Purchased S\$:		290.69
		10.00% Of The Above Parts S\$:		29.07
		Based On Cost Plus S\$:		319.76
E. & O.E.			Total S\$:	319.76

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg