

Section A - Accident Details

Registration Number	SHB5775J
Case Reference Number	TAX/05/22/2003
Registration Date	14/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	PANG KIN HUNG
Type of Accident	Head to Rear
Accident Date and Time	2/5/2022 12:45 PM
Accident Reported Date and Time	4/5/2022 10:13 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114801
Special Instruction to ARC, if any	TP/ REAR PORTION/ DROVE IN
Prepared Date and Time	4/5/2022 1:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$3,391.72	\$0.00
Total Other Cost	\$380.00	(\$100.00)
TOTAL COST	\$5,185.72	\$300.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / NTUC
ARC / Surveyor Sign Off Date	04/05/2022 5:17 PM	04/05/2022 4:15 PM
Signature		
Remarks	LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com	

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2022

User ID : PohSuan

		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
		8158147010	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
		8159147010	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
		5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
		5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given	X
Total					\$4,210.90		\$0.00			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	0.00	
+	200.00	
+	200.00	L/S \$300/-
	400.00	
	-20%	
	320.00	