



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS/LPC22004220/Kvy3m4

Date: 09/09/2022

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 2151H	Veh. Inspected	GBF 7681H
Policy No.	Z22VC05009408	Coverage (\$)	0.00
Claim No.	22/22/22/VC05/025760	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	06/05/2022

2. Vehicle Particulars & Condition

Make & Model	OPEL COMBO (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	W0L6WYL11G9593832	Colour	WHITE
Odometer	81723 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	MICHELIN	3 mm
L/H Front Tyre	195/60 R16	MICHELIN	3 mm
R/H Rear Tyre	195/60 R16	MICHELIN	4 mm
L/H Rear Tyre	195/60 R16	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/04/2022	Inspection Date	09/05/2022
Survey held at	160 Sin Ming Drive #02-04 Autocity, level #07-17		
Repairer	CAR TIMES AUTOLUTION PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------