



ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref :

305815005

Via Fax :

EMAIL

Date :

06.05.22

Your Insured :

8MS 5150W

Time of Fax :

Date of Acc :

05.05.22

Attn: Motor Claims Department

AXA

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 4505J

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

✦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
✦ Jumari Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
✦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
✦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

chiangli@edge.com.sg
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4505J

05.05.2022

MAKE REG 13.10.2016

MODEL HYU- I40

CHIANG/ AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
1	REAR BUMPER LOWER COVER			\$228.00
2	REAR BUMPER BRACKET SIDE /RH		\$35.60	\$35.60
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	TAIL LAMP RH			\$697.80
1	REAR WHEEL CAP			\$214.20
1	REAR FENDER RH			\$2,171.40
				\$3,922.00
				20.00%
				\$784.40
	DISCOUNTED TOTAL			\$3,137.60
1	REAR FENDER ADVERTISEMENT			\$100.00
1	REAR BUMPER ADVERTISEMENT			\$50.00
1	REAR BUMPER MAT			\$50.00
1	REVERSE SENSOR			\$135.70
				\$335.70
	Labour Charge			
	Panel Beating			\$850.00
	Spray Painting Charge			\$600.00
	Remove/Refix Upholstery			\$90.00
	Check lighting			\$60.00
	Tuff Kote			\$90.00
	TOTAL LABOUR			\$1,690.00
	ESTIMATE TOTAL			\$5,163.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				