

**AUTO UNITED SG PTE LTD**

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

GB71080284

TP Chin
Hi Peng

Page No. 1

Vehicle No. SMN1303S HONDA FREED

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BUMPER <i>born</i>		1290.00	841
1	REAR BUMPER REFLECTOR LAMP RH <i>new</i>		90.00	+
1	REAR BUMPER SIDE RETAINER RH <i>new</i>		110.00	58.
1	REAR FENDER RH <i>Repair</i>		1235.00	x
1	REAR FENDER INNER SHIELD RH <i>new</i>		170.00	+
1	REAR SLIDING DOOR RH <i>Dented</i>		1290.00	+
1	REAR SLIDING DOOR HANDLE RH <i>new</i>		105.00	+
1	REAR SLIDING DOOR INNER TRIM BOARD RH <i>new</i>		980.00	750
1	REAR SLIDING DOOR MOTOR RH <i>new</i>			+
1	REAR SLIDING DOOR LOCK RH <i>new</i>		620.00	+
1	REAR SLIDING DOOR RUBBER <i>new</i>		215.00	+
1	REAR POWER WINDOW MOTOR <i>new</i>		984.50	+
1	REAR ABSORBER RH <i>new</i>		410.00	+
1	REAR AXLE <i>new</i>		1520.00	+
1	REAR BEARING HUB RH <i>new</i>		350.00	+
1	FRONT FENDER RH <i>Dented</i>		1235.00	566
1	FRONT FENDER INNER SHEILD RH <i>new</i>		170.00	+
1	FRONT FENDER " HYBRID " EMBLEM <i>new</i>		98.90	+
1	FRONT DOOR RH <i>Dented</i>		1085.60	+
1	FRONT POWER WINDOW MOTOR <i>new</i>		984.50	387
1	LOWER SIDE SKIRT RH <i>Repair</i>		705	+
		5696.50		
		4557.20		
		less	20%	
			9369.50	
			1873.90	20%
			7495.60	
SPECIAL NETT ITEMS				
1 SET	REAR BUMPER CLIPS <i>new</i>		100.00	30
1	REAR RIM COVER RH <i>cut</i>		550.00	150
1	REAR TYRE RH <i>new</i>		410.00	+
1	REAR FENDER SEALANT <i>new</i>		100.00	+
1 SET	REAR FENDER INNER SHIELD CLIPS <i>new</i>		80.00	+
1	FRONT RIM COVER RH <i>cut</i>		550.00	150
1	FRONT TYRE RH <i>new</i>		410.00	+
1	FRONT FENDER SEALANT <i>new</i>		100.00	+
1	FRONT FENDER INNER SHIELD CLIPS <i>new</i>		80.00	+
		Total Parts	8735.60	330



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Page No. 2

Vehicle No. SMN1303S HONDA FREED

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	2000.00 900	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00 1200	
3	To remove and refix wiring at damaged areas	180.00 30	
4	To perform anti rust treatment on affected areas	150.00 60	
5	To remove and replace undercarriage part	200.00 80	
6	To conduct wheel alignment test	150.00 80	
	Labour Total :	4480.00	2350
TOTAL (PARTS & LABOUR):		13215.60	

Adrian Lj
H/S. 11/05/22.
06 Days

7237.20

total: ~~6368.72~~
L/S: ~~517K~~

17/10/22 check with Adrian 5700k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S.I.K.