

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	R	Ref:	CS/CTI22004250/Aty3		
	3 ANSON ROAD # SPRINGLEAF TOV	С	Date:	09/05/2022		
			C	Code:	СТІ	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNF 707Y	Veh. Inspected		SMN 1303S	
	Policy No.	DMPCSNW00095642201	Coverage (\$)		0.00	
	Claim No.	SNM22D202932/C02/SNF707Y/ TANCHC	Excess (\$)		0.00	
	Assign From	Jacqueline Tan	Assign Date		06/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5. General Information						
	Accident Date	05/05/2022	Inspection Date		10/05/2022	
	Survey held at	AUTO UNITED SG PTE LTD				
		13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.	Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						