



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM22004281/Uea3q2 Date: 08/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMC 7733C	Veh. Inspected	SMJ 3881Y
	Policy No.	GA575675	Coverage (\$)	0.00
	Claim No.	S2M040DC	Excess (\$)	0.00
	Assign From		Assign Date	09/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MR2B23F3001173445	Colour	BLACK
	Odometer	138116 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	KAPSEN	6 mm
	L/H Front Tyre	195/55 R15	KAPSEN	6 mm
	R/H Rear Tyre	195/55 R15	KAPSEN	6 mm
	L/H Rear Tyre	195/55 R15	KAPSEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/05/2022	Inspection Date	10/05/2022
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	