



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0136370 / CHINA TAIPING
Chassis No: JHMRV3800NS200068
License No: SNE1552A
Mileage: 6936
Engine No: L15ZK1100068

Document No: SVO22023283
Printed By: IVANTEO
Order Date: 23. May 2022
Order Time: 11:53:35 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHENG HSIAO LING OWNER INSURER: Tokio Marine ACC DATE: 06/05/2022 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: PC9130T SUPPLEMENTARY PART						
68100-3M0-E00ZZ	TAILGATE COMP	1	916.70	25	687.52	48.13	735.65
91513-T6A-003	CLIPTAILGATE SPOILER	9	2.60	25	17.55	1.23	18.78
75722-3N0-E01	EMBLEM SET,RR.	1	35.70	25	26.77	1.87	28.64
34150-3M0-J02	LIGHT ASSY,R.LID	1	463.00	25	347.25	24.31	371.56
04715-3M0-000ZZ	FACE,RR.BUMPER	1	564.20	25	423.15	29.62	452.77
71560-3M0-G00	FACE ASSY RR BPR	1	488.30	25	366.22	25.64	391.86
71630-3M0-003	SPACER,R.RR.BPR S	1	19.00	25	14.25	1.00	15.25
71680-3M0-003	SPACER,L.RR.BPR S	1	19.00	25	14.25	1.00	15.25
91505-TM8-003	CLIP,BUMPER	6	2.30	25	10.35	0.72	11.07
73213-3M0-000	RUBBER,R.WSHLD DA	1	12.70	25	9.52	0.67	10.19
73215-3M0-000	RUBBER,WSHLD DAM	1	26.60	25	19.95	1.40	21.35
73216-3M0-000	SPACER,RR.WINDSHIELD	2	2.90	25	4.35	0.30	4.65
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30
73263-3M0-000	RUBBER,L.WSHLD DA	1	12.70	25	9.52	0.67	10.19
91502-TTA-003	CLIP,RR.WINDSHIELD LOWER	2	4.30	25	6.45	0.45	6.90
91502-TXA-J01	CLIP,RR.WINDSHIELD UPPER	2	2.90	25	4.35	0.30	4.65
74895-3M0-U21ZD	GARNISH ASSY,TAILGATE LOWER	1	706.90	25	530.17	37.11	567.28
NMRS-S111-RETAINER	1 PCS SENSOR RETAINER	4	18.00		72.00	5.04	77.04
	SUM PARTS:				2,570.44	179.94	2,750.38
BOSUN		1	50.00		50.00	3.50	53.50
	SUNDRIES						
BML02I		1	280.00		280.00	19.60	299.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BKTG02R		1	650.00		650.00	45.50	695.50
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BG02R		1	650.00		650.00	45.50	695.50
	REPLACE RR. WINDSCREEN.(N)						
BA02R		1	280.00		280.00	19.60	299.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BC012R		1	480.00		480.00	33.60	513.60
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R		1	480.00		480.00	33.60	513.60
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BODAMKIT		1	100.00		100.00	7.00	107.00
	WINDSCREEN DAM KIT.						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0136370 / CHINA TAIPING	Document No:	SVO22023283			
Chassis No:	JHMRV3800NS200068	Printed By:	IVANTEO			
License No:	SNE1552A	Order Date:	23. May 2022			
Mileage:	6936	Order Time:	11:53:35 AM			
Engine No:	L15ZK1100068	Service Advisor:	IVAN TEO BOON KIAT			
BOJSE		1	100.00	100.00	7.00	107.00
	BODY JOINT SEALANT TAILGATE					
BKRP02S	1729	1	1,300.00	1,300.00	91.00	1,391.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.					
BP04R	1718	1	1,560.00	1,560.00	109.20	1,669.20
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)					
		SUM LABOUR:	5,930.00	415.10	6,345.10	
		TOTAL SGD	8,500.44	595.04	9,095.48	
		Total Payable (SGD)			9,095.48	

GST Amount is calculated from individual line(s)