

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: HL Assurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	22/HL/OD-226 (05)
Policy No:	MP316865	Date of Loss:	05/05/2022
Vehicle Reg. No.:	SLL83648	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FELIX OOI AIK SIONG	Contact No:	+6598458787
Driver:	FELIX OOI AIK SIONG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	13/03/2017
Vehicle Colour:	Silver		
Engine No:	1ZR591005	Chassis No:	MR053REH104556857
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

*Not allowed
Excess?
10/5/22
Tuber 7 hrs. return 7 days
4 days*

COST OF CLAIMS

	Amount
Parts	4,123.90
Miscellaneous Items	125.00
Labour	1,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,778.90
+ GST 7.00% (S\$)	404.52
Nett Amount (S\$)	6,183.42

This claim is handled by: CHIA PEI YING

Generated using Meriman e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 May 2022)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SME Motor Pte Ltd/SLL83848/07/05/2022 12:41
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>Surf/Sec</i>	0.00	0.00	*380.00 F ✓
2	1		*FRT BONNET LOCK <i>Ynt</i>	0.00	0.00	*65.00 F ✓
3	2		*FRT BONNET HINGE <i>R</i>	0.00	0.00	*90.00 F X
4	10		*FRT BONNET INSULATOR CLIP <i>17</i>	0.00	0.00	*20.00 F X
5	1		*FRT GRILLE <i>one</i>	0.00	0.00	*195.00 F ✓
6	4		*FRT GRILLE CLIP <i>del</i>	0.00	0.00	*8.00 F ✓
7	1		*FRT GRILLE TOP GARNISH <i>17</i>	0.00	0.00	*65.00 F X
8	1		*FRT BUMPER <i>Toon</i>	0.00	0.00	*235.00 F ✓
9	2		*FRT BUMPER RETAINER <i>del</i>	0.00	0.00	*78.00 F ✓
10	10		*FRT BUMPER CLIP <i>del</i>	0.00	0.00	*20.00 F ✓
11	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*75.00 F ?
12	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*175.00 F ?
13	2		*HEADLAMP <i>holder one</i>	0.00	0.00	*1,460.00 F ✓
14	1		*BRACE PANEL <i>del</i>	0.00	0.00	*55.00 F ✓
15	1		*AIRCON CONDENSER	0.00	0.00	*350.00 F ?
16	1		*RADIATOR	0.00	0.00	*480.00 F ?

F=Franchise part.

Sub Total (S\$) 3,749.00
 + Margin on L,N Items 10.00% (S\$) 374.90
Total Parts (S\$) 4,123.90

SME Motor Pte Ltd/SLL83848/07/05/2022 12:41. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT BONNET SEALANT <i>all</i>	60.00 <i>40</i>
2	1	FRT NUMBER PLATE <i>Best</i>	40.00 <i>35</i>
3	1	RADIATOR COOLANT	25.00 <i>?</i>
Sub Total (S\$)			125.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 <i>?</i>
3	LABOUR CHARGE	New	700.00 <i>1200</i>
4	SPRAY PAINTING	New	700.00 <i>540</i>
Gross Labour Cost (S\$)			1,830.00

SME Motor Pte Ltd/SLL83848/07/08/2022 12:41. Not valid without Reference section.
 Generated using Merimen a-Claims IEAS

< END OF ESTIMATES >

ENTERED 0 JUL 2012