

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	GREAT AMERICAN	N INSURANCE COMPANY	Re	ef:	CS/GAI22004309/Uqy3m4	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	AL TOWER	Da	ate:	01/06/2022	
			Co	ode:	GAI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YP 8065E	Veh. Inspected		SLT 4735P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CLMOMVC000004160	Excess (\$)		0.00	
	Assign From	SHERY WONG	Assign Date		09/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FREED HYBRID	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	GB71033175	Colour		BLUE	
	Odometer	47243 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	CONTINENTAL		6 mm	
	L/H Front Tyre	205/55 R16	CONTINENTAL		6 mm	
	R/H Rear Tyre	205/55 R16	CONTINENTAL		6 mm	
	L/H Rear Tyre	205/55 R16	CONTINENTAL		6 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/05/2022	Inspection Date		09/05/2022	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					