









Home Team Agency

SCOPE OF WORK

To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

Scope Of Work

CONTRACTOR:	ACTOR: STRIDES VEH TYPE: MB UNIT: ICA HQ					 	Reference No.	6930/ICA/4W/22/04/01
VEH NO:	GBH6930	K	REPAIR TYPE:		ACCIDENT			
VEH MAKE/MODEL:	HYUNDAI STAREX		ODOMETER:		15595		iLMS No.	-

S/N		PARTS DESCRIPTION		QTY		Parts Cost Per Unit (\$)	6930/ICA/4W/22/04/0	
1	1 Scope Of Repairs							
1.1	1.1 Rear LH Corner Panel Garnish			1		108.90	108.90	
2								
2.1			0		0.00	0.00		
	Remarks: Pricing on this quotation is valid for 1 month.					Parts Total:	\$ 108.	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)		Man-Hour Qty	Total Man-Hour Cost (\$)		
1	Scope Of Repairs						
1.1	Remove, Replace & Spray Paint for Rear LH Corner Panel Garnish 68.00				68.00		
1.2	.2 Panel Beat & Spray Paint for Rear LH Panel damaged area				68.00		
		SUB	-TOTAL		\$	136.00	
2	Additional Services						
2.1	Collection Service From Station to Workshop (SOR 9)	61.	.20		(51.20	
2.2	.2 Return Service From Workshop to Station (SOR 9) 61.20				(51.20	
•	SUB-TOTAL						
			Lab	our Total:	\$	258.40	
GRAND TOTAL: \$						367.30	
Contractor shall complete the entire repair within 15 working days upon approval date . (Include parts awaiting time)							
Contractor shall provide Road Test & Health Check after CVR repair completed within 7 working days. (Include CMA repair if any)							

Verification of Scope of Work								
Contractor QC		Vetted By:		Approved By:				
Name:	KONG SEW KUI	Name:		Name:				
Date:	09.05.2022	Date:		Date:				
Sign:	Hote	Sign:		Sign:				
Verification of Completed Repairs								
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager				
Name:		Name:		Name:				
Date:		Date:		Date:				
Sign:		Sign:		Sign:				
All completed renairs must be verified by Home Team Contract Manager / Fleet Manager before nayment can be made								