

Not Attached
Recovery B4 paint

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9358T

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

09 MAY 2022

SHD9358T

JTDKB3FU803082136

200303878K

TOYOTA

PRIUS

23/04/2022

SLP5628E/TOKIO

25/01/2019

PART		LIST	
1	COVER, FRONT BUMPER	\$	516.00 ✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	79.60 X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	716.60 X
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	47.50 X
1	BRACKET, FRONT BUMPER SIDE, RH	\$	59.30 X
1	LAMP ASSY, FOG, RH	\$	951.40 7
1	UNIT ASSY, HEADLAMP, RH	\$	2,637.60 X
1	JAR ASSY, WINDSHIELD WASHER	\$	219.10 X
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	1,436.60 X
1	RIM	\$	1,900.10 ✓
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80 X
1	FENDER SUB-ASSY, FRONT RH	\$	977.80 ✓
1	EMBLEM, SIDE PANEL RH	\$	54.60 ✓
1	LINER, FRONT FENDER, RH	\$	206.70 X
TOTAL		\$	10,397.70
25%		\$	2,599.43
		\$	7,798.28

Special Nett

1	FRT BUMPER CLIP	\$	65.00 ✓
1	TYRE	\$	350.00 X
1	FENDER CLIP	\$	65.00 X
1	FENDER LINER CLIP	\$	65.00 X
1	FRT LH BUMPER RETAINER CLIP	\$	65.00 X
TOTAL		\$	610.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9358T**AAD2204-**

TOTAL PARTS	\$	8,408.28
--------------------	-----------	-----------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	<i>na</i>	380.00	<i>X</i>
----	-----------	--------	----------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		1,400.00	<i>3001</i>
----	--	----------	-------------

Putty And Spray Painting Of The Affected Portion.

\$		1,400.00	<i>4401</i>
----	--	----------	-------------

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$		240.00	<i>301</i>
----	--	--------	------------

To Check Electrical Lighting Concerned.

\$		170.00	<i>151</i>
----	--	--------	------------

TOTAL	\$	3,590.00
--------------	-----------	-----------------

Over All Total	\$	11,998.28
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days*20 days**2 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**